

NYSDEC SPILL REPORT FORM



DEC REGION: SPILL NAME:				NUMBER: EAD:	0101108 RJBRAZEL		
CALLER NAME CLR'S AGENC CALLER'S PHO	Y: NEW V	SS PRINCE ENTURE GEAR 38-2716	NOTIFI	ER'S NAME: ER'S AGENCY: ER'S PHONE:	NEW VE		AR
SPILL DATE: CALL RECEIV	/ED DATE:	04/28/2001 04/28/2001	SPILL TIME: RECEIVED TIME	4:00 pm : 6:22 pm		DISPATCH	ER:
PLACE: STREET: CONTACT:	PHYLISS F	URE GEAR VENTURE GEAR DRIVE	TOW COM CON	NTY: /N/CITY: IMUNITY: ITACT PHONE: L REPORTED B	(315) 4	known ***** YRACUSE 38-2716	
FACILITY TY		mmercial/Industrial	<u> </u>	ERBODY:	T: Nespo	risible Faity	
valve on he		ed - optec enironmental in	cleaning up now -	almost complete			
MATERIAL ube oil		CLASS Petroleum	SPILLED 0.00 G	0.00 G		RESOURCI Soil,	ES AFFECTED
COMPANY NEW VENTURE	E GEAR	POTI ADDRESS 6600 NEW VENTU	ENTIAL SPILLE		PHYI	TACT LISS PRINC) 438-2716	E
Tank No. Tank	Size Mater	ial Cause	Source	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 20 CLOSED BY CM	04 data trans	slation this spill Lead_DEC	Field was "RB"				
PIN		T & A	COST CENTER				

Created On: 04/28/2001 FOIL195975

Date Printed: 12/12/2018 Last Updated: 06/05/2001 1

MEETS STANDARDS:

False

CLOSE DATE: 06/05/2001



NYSDEC SPILL REPORT FORM



DEC REGION: SPILL NAME:	7 NEW VENTU	RE GEAR		SPILL NU		01026 MENA		
CALLER NAME CLR'S AGENC' CALLER'S PHO		TURE GEAR		NOTIFIER	R'S NAME: R'S AGENCY: R'S PHONE:	SUPER SAME	VISOR	
SPILL DATE: CALL RECEIV	ED DATE:	06/10/2001 06/11/2001	SPILL TI	ME: ED TIME:	10:00 am 11:59 am		DISPATCH	ER:
PLACE:	NEW VENTURE		ILL LOC	ATION COUN	ΓY:	Ononda	nga	
STREET:		TURE GEAR DRIVE		TOWN	CITY: UNITY:		known **** SYRACUSE	
CONTACT:	PHYLISS PRIN	ICE		CONT	ACT PHONE:	(315) 4	138-2716	
CONT. FACTO		Error ercial/Industrial			REPORTED B RBODY:	Y: Respo	onsible Party	
CALLER REI WAS DUM	_	TALLY INTO STORM D	DRAIN, AL	L BUT 1 Q	UART WAS CI	LEANED	UP.	
MATERIAL unknown petrolei	um	CLASS Petroleum		SPILLED 20.00 G	RECO 19.00	VERED G	RESOURC Sewer,	ES AFFECTED
COMPANY NEW VENTURE	E GEAR	POTI ADDRESS 6600 NEW VENTU		SPILLER	_	E N PHY	ITACT 'LISS PRINC) 438-2716	E
Tank No. Tank	Size Material	Cause	Soi	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 20		on this spill Lead_DEC	Field was	"MN"				
<u>PIN</u>	<u>T 8</u>	<u> </u>	COST CI	<u>ENTER</u>				

Created On: 06/11/2001 FOIL195976

Date Printed: 12/12/2018 Last Updated: 06/12/2001 2

MEETS STANDARDS:

False

CLOSE DATE: 06/12/2001



NYSDEC SPILL REPORT FORM



DEC REGION: SPILL NAME:	7 NEW VENTURE GEA	AR		SPILL NU		01038 CFM <i>P</i>	886 ANNES	
CALLER NAME CLR'S AGENC' CALLER'S PHO		GEAR		NOTIFIER	R'S NAME: R'S AGENCY: R'S PHONE:		ENTURE GE	AR
SPILL DATE: CALL RECEIV	07/12/ ZED DATE: 07/12/		SPILL T	IME: ED TIME:	8:00 am 8:21 am		DISPATCH	ER:
PLACE: STREET: CONTACT:	NEW VENTURE GEAR 6600 NEW VENTURE	R	ILL LOC	COMM		EAST S	aga Iknown ***** SYRACUSE 431-7089	
CONT. FACTO				•	REPORTED B	Y: Respo	onsible Party	
CALLER REI	MARKS: er - op-tech coming to do	clean up						
MATERIAL motor oil		CLASS Petroleum		SPILLED 1.00 G	RECO 0.00 G	VERED	RESOURC Soil,	ES AFFECTED
COMPANY NEW VENTURE		<u>POTI</u> DRESS 10 NEW VENTU		SPILLEF	_		NTACT	
Tank No. Tank	Size Material	Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 20	KS: 04 data translation this s	spill Lead_DEC	Field was	: "CM"				
<u>PIN</u>	<u>T & A</u>		COST C	ENTER				

Created On: 07/12/2001 FOIL195977

Date Printed: 12/12/2018 Last Updated: 07/19/2001 3

MEETS STANDARDS:

False

CLOSE DATE: 07/19/2001





DEC REGION: SPILL NAME:		/ VENTURE GI	EAR		SPILL NU		0104015 CFMANNES		
CALLER NAME CLR'S AGENCY CALLER'S PHO	Y : N	M BROWN EW VENTURE 15) 431-7089	GEAR		NOTIFIEI NOTIFIEI	R'S NAME: R'S AGENCY: R'S PHONE:	SAME		
SPILL DATE:	/ED DA		1/2001 5/2001	SPILL T	IME: ED TIME:	9:00 am 10:41 am		DISPATCH	IER:
			ęp.	ILL LOC	ATION				
PLACE: STREET: CONTACT:	6600 N	VENTURE GEA			COUN TOWN		EAST S	nknown ***** SYRACUSE	
CONTACT.	JIIVI DI	ICOVIN			_ CONT	ACT PHONE.	(313)2	431-7089	
CONT. FACTO	_	Tank Overfill Commercial/	ndustrial			REPORTED E RBODY:	Y : Affect	ted Persons	
CALLER REM overfill of u		: n up crew on th	e way						
MATERIAL transmission fluid	d		CLASS Petroleum		SPILLED 2.00 G	RECO 0.00 (VERED	RESOURC Soil,	ES AFFECTED
COMPANY NEW VENTURE	E GEAR		POT DDRESS 600 NEW VENTU		SPILLEF	<u> </u>		NTACT LER	
Tank No. Tank	Size N	/laterial	Cause	So	urce	Test Meth	iod	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 200		translation this	spill Lead_DEC	Field was	"CM"				
PIN		T & A		COST C	ENTER				
CLASS: C3	(CLOSE DATE:	07/19/2001		MEETS ST	ΓANDARDS:	False		

Created On: 07/16/2001 FOIL195978

Date Printed: 12/12/2018 Last Updated: 07/19/2001 4





DEC REGION:						SPILL NUMBER:			0104684		
SPILL NAME:	NE	W VENT	URE GE	AR		DEC LEA	AD:	MENA	ASH		
CALLER NAM	E:	JIM BRO	WN			NOTIFIER	R'S NAME:				
CLR'S AGENC	Y:!	NEW VE	NTURE (GEAR		NOTIFIER	R'S AGENCY:				
CALLER'S PH	ONE <u>: (</u>	315) 431	-7089			NOTIFIER	R'S PHONE:				
SPILL DATE:			08/01	/2001	SPILL T	IME:	8:15 am		DISPATCH	ER:	
CALL RECEIV	/ED D	ATE:	08/01/	/2001	RECEIV	ED TIME:	10:12 am		-		
				<u>SP</u>	ILL LOC	ATION					
PLACE:	NEW	VENTU	RE GEA	₹		COUN	TY:	Ononda	aga		
STREET:	6600	NEW VE	NTURE	GEAR DRIVE		TOWN			nknown *****		
CONTACT	111/4	BROWN				-	IUNITY:		SYRACUSE		
CONTACT:	JIIVI	BROWN				_ CONTA	ACT PHONE:	(315)	431-7089		
CONT. FACTO	R:		ment Fa			SPILL	REPORTED B	Y: Resp	onsible Party		
FACILITY TY	PE:	Comr	nercial/Ir	ndustrial		WATE	RBODY:				
				SED RELEASE DRM - SUBSTA CLASS Other			DAP	VERED	RESOURCE Soil,	ES AFFECTED	
				<u>POT</u>	ENTIAL	SPILLER	<u>RS</u>				
COMPANY NEW VENTURE	E GEA	R		DDRESS 00 NEW VENT	URE GEA	R DR EAS	ST SYRACUSE		NTACT LER		
Tank No. Tank	Size	Materia	I	Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure	
DEC REMAR	RKS:										
Prior to Sept, 20	04 dat	a transla	tion this	spill Lead_DEC	Field was	s "MN"					
<u>PIN</u>		<u>1</u>	Г& A		COST C	ENTER					
CLASS: C5		CLOSE	DATE:	10/09/2001		MEETS ST	TANDARDS:	False			

Created On: 08/01/2001 FOIL195979

Date Printed: 12/12/2018 Last Updated: 10/09/2001 5





DEC REGION: SPILL NAME:		TURE GEAR		SPILL NU		0160011 CFMANNES		
CALLER NAME CLR'S AGENC CALLER'S PHO	Y: NEW VE	S PRINCE NTURE GEAR 8-2716		NOTIFIE	R'S NAME: R'S AGENCY: R'S PHONE:			
SPILL DATE: CALL RECEIV	/ED DATE:	05/25/2001 05/25/2001	SPILL T	IME: ED TIME:	9:00 am 10:30 am		DISPATCH	IER:
			SPILL LOC	CATION				
PLACE:	NEW VENTU			COUN	TY:	Ononda	ıga	
STREET:	6600 NEW VE	ENTURE GEAR		_ _ TOWN		Dewitt		
				_	IUNITY:	DEWIT		
CONTACT:	PHYLISS PR	RINCE		CONT	ACT PHONE:	(315) 4	138-2716	
CONT. FACTO	R: Equip	pment Failure		SPILL	REPORTED B	Y: Respo	onsible Party	,
FACILITY TY	PE: Com	mercial/Industrial		WATE	RBODY:	COLL	ECTION PO	ND
	OWER OUTA	GE COOLING SYST						
MATERIAL antifreeze		CLAS Other	S	SPILLED 80.00 G	RECO 0.00 G	VERED	RESOURC SW,	ES AFFECTED
		Р	OTENTIAL	SPILLEF	RS			
COMPANY NEW VENTURE	E GEAR	ADDRESS 6600 NEW VE	NTURE GEA	R DR EAS	ST SYRACUSE	PHY	ITACT LISS PRINC) 438-2716	CE
Tank No. Tank	Size Materia	al Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 20		ation this spill Lead_[DEC Field was	s "CM"				
PIN	-	Т & А	COST C	<u>ENTER</u>				
CLASS: D5	CLOSE	E DATE: 05/28/200	1	MEETS ST	ΓANDARDS:	False		

Created On: 05/29/2001 FOIL195980
Date Printed: 12/12/2018 Last Updated: 05/29/2001 6





DEC REGION:	7			PILL NU	MDED.	02110	100		
SPILL NAME:		URE GEAR	 -	EC LEAD		MENA			
— TEL NAME.		011L 0L/111			··	1412147	1011		
CALLER NAME	: PHYLLIS	PRINCE	N	OTIFIER'	S NAME:	POM SU	JLLIVAN		
CLR'S AGENCY	Y: NEW VE	NTURE GEAR	N	OTIFIER'	S AGENCY:	NEW VE	ENTURE GE	AR	
CALLER'S PHO	ONE: (315) 438	3-2716	N	OTIFIER'	S PHONE:	(315) 43	8-2716		
SPILL DATE:		02/05/2003	SPILL TIME		10:00 am		DISPATCH	IER:	
CALL RECEIV	ED DATE:	02/05/2003	RECEIVED	TIME: _	11:30 am				
		SP	ILL LOCA	TION					
PLACE:	NEW VENTUI			COUNT	Y :	Ononda	ıga		
STREET:	6600 NEW VE	NTURE GEAR DRIVE		TOWN/C	CITY:	***** Un	known ****		
				COMMU	JNITY:	EAST S	YRACUSE		
CONTACT:	PHYLLIS PR	INCE		CONTA	CT PHONE:	(315) 4	138-2716		
CONT. FACTO	R: Huma	an Error		SPILLE	REPORTED B	Y ·l ocal	Agency		
FACILITY TY		mercial/Industrial		WATER		11 2000.	, .geey		
CALLER REN SPILL NEX	MARKS: (T TO A PONE)							
MATERIAL		CLASS		PILLED		VERED		ES AFFECT	ΓED
waste oil/used oil		Petroleum	10).00 G	0.00 G	ı	Soil,		
		POT	ENTIAL SE	PILLERS	<u>S</u>				
COMPANY		ADDRESS				CON	ITACT		
WASTE MANAG	SEMENT	SYRACUSE N	Y 13057-			SUE	ROSSI		
						(585) 494-3000	225	
Tank No. Tank	Size Materia	I Cause	Sourc	e:e	Test Meth	od	Leak Rate	Gross Fail	ure
DEC REMAR	KS:								
		tion this spill Lead_DEC	Field was "M	1N"					
, ,									

PIN T & A COST CENTER

CLASS: C5 **CLOSE DATE:** 02/05/2003 **MEETS STANDARDS:** False

02/05/2003 Created On: FOIL195981 7 Last Updated: 02/05/2003 Date Printed: 12/12/2018





DEC REGION:	7			SPILL N	JMBER:	03034	170	
SPILL NAME:	NEW VENTURE GE	AR		DEC LEA	ND:	CFMA	ANNES	
CALLER NAME:	: TOM SULLIVAN			NOTIFIEI	R'S NAME:	TOM SI	JLLIVAN AT	
CLR'S AGENCY	: NEW VENTURE	GEAR		NOTIFIEI	R'S AGENCY:	NEW VI	ENTURE GE	AR
CALLER'S PHO	NE: (315) 438-2765			NOTIFIE	R'S PHONE:	(315) 43	38-2765	
SPILL DATE:	07/02	/2003	SPILL T	IME:	2:00 pm		DISPATCH	ER:
CALL RECEIVE	D DATE : 07/02	/2003	RECEIV	ED TIME:	2:32 pm			
		SPI	LL LOC	ATION				
PLACE:	NEW VENTURE GEA	R		COUN	TY:	Ononda	aga	
STREET:	6600 NEW VENTURE	GEAR DRIVE		TOWN			ıknown *****	
-				COMM	IUNITY:	EAST S	SYRACUSE	
CONTACT:	TOM SULLIVAN			CONT	ACT PHONE:	(315)	138-2765	
CONT. FACTOR	R: Human Error			SPILL	REPORTED B	Y: Resp	onsible Party	
FACILITY TYP	PE: Commercial/I	ndustrial		WATE	RBODY:			
CALLER REM DRIVER SP	IARKS: PEARED DRUM WITH	FORK LIFT						
MATERIAL other -		CLASS Other		SPILLED 2.00 G	RECO 2.00 G	VERED	RESOURC Soil,	ES AFFECTED
		POTI	ENTIAL	SPILLEF	RS			
COMPANY NEW VENTURE		DDRESS 00 NEW VENTU	JRE GEAI	R DR EA	ST SYRACUSE	E N TON		
						(315) 438-2765	
ank No. Tank \$	Size Material	Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMARK	(S:							
The material spille	4 data translation this ed was magnesium mareatment system wher	achinery coolant	, 4% solu	tion. optect	vaccumed the	product	and placed ir	nto

PIN T & A COST CENTER

CLASS: C5 CLOSE DATE: 07/10/2003 MEETS STANDARDS: False

Created On: 07/02/2003 FOIL195982

Date Printed: 12/12/2018 Last Updated: 07/22/2003 8





DEC REGI	-							SPILL NUMBER: DEC LEAD:				0304959 RJBRAZEL		
CALLER N	ENCY:		IEW VE	PRINCE NTURE (3-2716	GEAR		NOTI	IFIEF	R'S NAME: R'S AGENCY R'S PHONE:	': EM	Р	RENS 88-2716		
SPILL DA		D DA	ATE:	08/11			_ .L TIME: EIVED TIN	ΛE:	6:30 am 7:40 am		_	DISPATCE	HER:	
						SDILL	OCATIO	N						
PLACE: STREET	_			RE GEAF	R DR	<u> JFILL L</u>	co	DUN'	TY: /CITY:		onda ** Ur	aga aknown *****		
OTIVEET	· <u> </u>	-	<u> </u>	(L OL) (I	(BI (UNITY:			YRACUSE		
CONTAC	СТ: _	PHYI	LISS PR	INCE			co	ТИС	ACT PHONE	: (3	15) 4	138-2716		
CONT. FA	CTOR	:	Unkn	own			SF	PILL	REPORTED	BY : R	Respo	onsible Party	l	
FACILIT	Y TYP	E:	Comr	mercial/Ir	ndustrial		W	ATEI	RBODY:					
CALLER SPILL WAY			_	S HAS'N	T REACHE	D WATER	WAY YET	TT F	IAS BEEN B	OOME	ED S	PILL CREW	ON THE	
MATERIAL quenching o	oil				CLAS Petrol	_	SPILL 5.00 (REC 0.00	OVER G	RED	RESOURC Soil,	ES AFFECTED	
COMPANY NEW VENT		GEAI	₹		DRESS		AL SPIL GEAR DR		RS ST SYRACUS	SE N	PHY	ITACT 'LISS PRINC) 438-2765	CE	
Tank No.	Tank S	ize	Materia	I	Cause		Source		Test Me	thod		Leak Rate	Gross Failure	
DEC RE Prior to Sep			a transla	tion this	spill Lead_[DEC Field	was "RB"							
PIN			1	Г&А		cos	T CENTER	₹						
CLASS:	C4		CLOSE	DATE:	10/22/200	3	MEET	S ST	ANDARDS:	Fal	lse			

Created On: 08/11/2003 FOIL195983

Date Printed: 12/12/2018 Last Updated: 10/22/2003 9





DEC REGION: SPILL NAME:	7 NE	W VENTUR	E GEAR			SPILL N DEC LE		0306290 MENASH			
CALLER NAME CLR'S AGENCY CALLER'S PHO	/: <u> </u>	THOMAS SINEW VENT	JRE GEA	R		NOTIFIE	R'S NAME: R'S AGENCY: R'S PHONE:		ENTURE GE	AR	
SPILL DATE: CALL RECEIVE	ED D		09/14/200 09/14/200		SPILL T	TIME: /ED TIME:	11:00 am 1:20 pm		DISPATCH	ER:	
				SP	III I O	CATION					
PLACE:	NEW	VENTURE	GEAR	<u> </u>		COUN	ITY:	Ononda	aga		
STREET:	6600	NEW VENT	URE GEA	AR DRIVE		_	I/CITY:		nknown *****		
						COM	IUNITY:	EAST S	SYRACUSE		
CONTACT:	TOM	1 SULLIVAN	l			CONT	ACT PHONE:	(315)	438-2765		
CONT. FACTO	R:	Unknow	n			SPILL	REPORTED E	3Y : Other			
FACILITY TY	PE:	Unknow	n				RBODY:		LING POND		
caller states the storm s	s at le	ast 20 gallo			ns have b	een placed	- spill is contair	ned - app	ears to be co	oming from	
MATERIAL quenching oil				CLASS Petroleum	ı	SPILLED 0.00 G	RECO 0.00 (VERED	RESOURC SW,	ES AFFECTED	
				POT	ENTIAL	SPILLEI	RS				
COMPANY UNKNOWN			ADDRE NY					CON	NTACT		
Tank No. Tank	Size	Material	(Cause	So	ource	Test Meth	od	Leak Rate	Gross Failure	
DEC REMAR Prior to Sept, 200		a translatio	n this spill	Lead_DEC	Field wa	s "MN"					
<u>PIN</u>		T &	A		COST	ENTER	_				
CLASS: C5		CLOSE DA	ATE : 09/	/15/2003		MEETS S	TANDARDS:	False			

FOIL195984 Last Updated: 09/15/2003 Date Printed: 12/12/2018 10

09/14/2003 Created On:





DEC REGION: SPILL NAME:	-	URE GEAR		SPILL NI		0308123 CFMANNES		
CALLER NAME CLR'S AGENC CALLER'S PHO	Y: NEW VEI	NTURE GEAR		NOTIFIE	R'S NAME: R'S AGENCY: R'S PHONE:	CONTACTOR		
SPILL DATE: CALL RECEIV	ED DATE:	10/31/2003 10/31/2003	SPILL T	IME: ED TIME:	2:30 pm 3:06 pm		DISPATCH	IER:
			SPILL LOC	CATION				
PLACE: STREET:		RE GEAR ENTURE GEAR DRIV		COUN TOWN	I/CITY: IUNITY:		aga nknown ***** SYRACUSE	
CONTACT:	PHYLLIS PR	INCE		CONT	ACT PHONE:	(315)	438-2716	
CONT. FACTO		r mercial/Industrial		_	REPORTED B	Y: Resp	onsible Party	
FACILITY TY	PE:	TICTOIAI/TITAUSTITAI		WAIL	RBODY:			
		THE CONTACTOR V	VAS DOING	EXCAVATI	ION OF THE C	ONTAIN	MENT AREA	AND FOUND
MATERIAL waste oil/used oi	I	CLASS Petrole		SPILLED 0.00 G	RECO 0.00 (VERED	RESOURC Soil,	ES AFFECTED
		PC	OTENTIAL	SPILLER	RS			
COMPANY NEW VENTURE	E GEAR	ADDRESS 6600 NEW VEN			<u> </u>	E N PHY	NTACT /LISS PRINC 5) 438-2765	E
Tank No. Tank	Size Materia	l Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 20		ition this spill Lead_D	EC Field was	s "CM"				
PIN	<u>1</u>	Г&А	COST C	ENTER				
CLASS: C3	CLOSE	E DATE: 03/18/2004	ļ.	MEETS ST	ΓANDARDS:	False		

Created On: 10/31/2003 FOIL195985

Date Printed: 12/12/2018 Last Updated: 03/18/2004 11





DEC REGION:	7			SPILL NU	JMBER:	03085	506	
SPILL NAME:	NEW VENTURE	GEAR		DEC LEA	.D:	CFMA	ANNES	
CALLER NAMI					R'S NAME:	JAY TA	LOR CONST	RUCTION
CLR'S AGENC	Y: NEW VENTUR	RE GEAR			R'S AGENCY:			
CALLER'S PHO	ONE: (315) 438-271	6		NOTIFIER	R'S PHONE:			
SPILL DATE:	11	/12/2003	SPILL T	ME:	7:00 am		DISPATCH	ER:
CALL RECEIV	YED DATE : 11	/12/2003	RECEIV	ED TIME:	9:24 am			
		SP	ILL LOC	ATION				
PLACE:	NEW VENTURE G	EAR		COUNT	ΓΥ:	Ononda	aga	
STREET:	6600 NEW VENTU	RE GEAR DRIVE		TOWN			known *****	
				•	UNITY:		SYRACUSE	
CONTACT:	PHYLLIS PRINCE			CONTA	ACT PHONE:	(315) 4	138-2716	
CONT. FACTO	OR: Other			SPILL	REPORTED B	Y: Respo	onsible Party	
FACILITY TY	PE: Commercia	al/Industrial		WATE	RBODY:			
CALLER RE DAMAGEI	MARKS: D INDUSTRIAL WAS	STE DRAIN						
MATERIAL waste oil/used oi	I	CLASS Petroleum		SPILLED 0.00 G	RECO 0.00 G	VERED	RESOURC Soil,	ES AFFECTED
		POT	ENTIAL	SPILLER	<u>IS</u>			
COMPANY NEW VENTURE	E GEAR	ADDRESS 6600 NEW VENTU	JRE GEAF	RDR EAS	ST SYRACUSE	PHY	ITACT 'LISS PRINC) 438-2765	E
Tank No. Tank	Size Material	Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 20	RKS: 04 data translation t	his spill Lead_DEC	Field was	"CM"				
PIN	T & A	<u>.</u>	COST C	ENTER				
CLASS: C3	CLOSE DAT	E: 05/04/2004		MEETS ST	ANDARDS:	False		

Created On: 11/12/2003 FOIL195986

Date Printed: 12/12/2018 Last Updated: 05/05/2004 12





DEC REGION: SPILL NAME:		L PROPERTY		SPILL NU		03109 CFMA	955 ANNES	
CALLER NAME CLR'S AGENC' CALLER'S PHO	Y: NEW VEI	NTURE GEAR		NOTIFIE	R'S NAME: R'S AGENCY: R'S PHONE:	NEW VE		AR
SPILL DATE: CALL RECEIV	ED DATE:	12/24/2003 12/24/2003	SPILL T	IME: ED TIME:	11:15 am 11:15 am		DISPATCH	IER:
			SPILL LOC	ATION				
PLACE:	COMERCIAL			COUN	TY:	Ononda	aga	
STREET:	6600 NEW VE	NTURE GEAR RD		TOWN	I/CITY:	***** Ur	ıknown *****	
				COMM	IUNITY:	EAST S	YRACUSE	
CONTACT:	PHYLIS PRIN	NCE		CONT	ACT PHONE:	(315) 4	138-2716	
CONT. FACTO	R: Unkn	own		SPILL	REPORTED B	Y: Other		
FACILITY TY	PE: Comr	mercial/Industrial		WATE	RBODY:			
	RED IN A CON	STRUCTION JOB, \ . WILL BE CLEANIN						
MATERIAL waste oil/used oi	I	CLAS Petrolo		SPILLED 0.00 L	RECO 0.00 L	VERED	RESOURC Soil,	ES AFFECTED
		Р	OTENTIAL	SPILLER	RS			
COMPANY COMERCIAL PR	ROPERTY	ADDRESS 6600 NEW VE	NTURE GEA	R RD EA	ST SYRACUSE	E N PHY	ITACT 'LIS PRINCE) 438-2716	
Tank No. Tank	Size Materia	I Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 20		tion this spill Lead_[DEC Field was	s "CM"				
PIN	1	⁻ & А	COST C	ENTER				
CLASS: C3	CLOSE	DATE: 03/18/200	4	MEETS ST	ΓANDARDS:	False		

Created On: 12/24/2003 FOIL195987

Date Printed: 12/12/2018 Last Updated: 03/18/2004 13



CLASS: C3

CLOSE DATE: 04/13/2004

NYSDEC SPILL REPORT FORM



DEC REGION: SPILL NAME:		ATER TREAT	MENT PLA	<u> </u>	SPILL NU	_	03132 CFMA	91 NNES	
CALLER NAME CLR'S AGENC CALLER'S PHO	Y: NEW VE	NTURE GEA	.R		NOTIFIE	R'S NAME: R'S AGENCY: R'S PHONE:			AR
SPILL DATE: CALL RECEIV	/ED DATE:	03/03/200		SPILL TI	ME: ED TIME:	5:00 pm 5:35 pm		DISPATCH	ER:
PLACE: STREET: CONTACT:	WASTE WAT	ENTURE GEA	ENT PLA	ILL LOC	COUN'		EAST S	ga known **** YRACUSE 138-2716	
CONT. FACTO			SPILL REPORTED BY: Other WATERBODY:						
they think	orgot to unhoo	the storm dr				out about 50 ga leaned up. the			
MATERIAL unknown non-pe	tro/non-haz ma	aterial	CLASS Other		SPILLED 50.00 G	RECO 0.00 G	VERED	RESOURC Soil,	ES AFFECTED
			POT	ENTIAL	SPILLEF	<u>RS</u>			
COMPANY UNITED OIL(NO	DRLITE)	ADDR I ALB	ESS ANY NY				DAV	I TACT ECARABET) 537-3223	A
Tank No. Tank	Size Materia	ıl (Cause	Soi	ırce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 20		ation this spill	Lead_DEC	Field was	"CM"				
<u>PIN</u>	-	Т & А		COST CI	ENTER				

Created On: 03/03/2004 FOIL195988

Date Printed: 12/12/2018 Last Updated: 04/13/2004 14

MEETS STANDARDS:

False



PIN

NYSDEC SPILL REPORT FORM



DEC REGION:				_ SPILL N	UMBER:	0313292			
SPILL NAME:	WASTE WA	ATER TREATMENT	PLA	_ DEC LEA	AD:	CFMA	NNES		
CALLER NAME	E: PHYLIS	PRINCE		NOTIFIE	R'S NAME:	PHYLIS PRINCE			
CLR'S AGENC	Y: NEW VE	NTURE GEAR		NOTIFIE	R'S AGENCY:	NEW VE	NTURE GE	AR	
CALLER'S PHO	ONE: (315) 438	8-2716		NOTIFIE	R'S PHONE:	(315) 43	8-2716		
SPILL DATE:		03/03/2004	SPILL 1	ГІМЕ:	5:00 pm		DISPATCH	IER:	
CALL RECEIV	/ED DATE:	03/03/2004	RECEIV	/ED TIME:	5:39 pm				
			SPILL LO	CATION					
PLACE:	WASTE WAT	ER TREATMENT P		COUN	ITY:	Ononda	ıga		
STREET:	6600 NEW VE	ENTURE GEAR RD			N/CITY:		known *****		
				_	MUNITY:		YRACUSE		
CONTACT:	CONTACT: PHYLIS PRINCE				CONTACT PHONE: (315) 438-2716				
CONT. FACTOR: Other SPILL REPORTED BY: Other									
FACILITY TYPE: Tank Truck WATERBODY:									
FACILITY TY	PE: Tank	Truck		_ WATE	RBODY:				
CALLER REI the driver f they think	MARKS: forgot to unhoc	ok the hose from the othe storm drain. so		and it spilled	l out about 50 g				
CALLER REI the driver f they think	MARKS: forgot to unhoc went down into the storm drain	ok the hose from the o the storm drain. so	me of the spill	and it spilled	I out about 50 g cleaned out. the	y have a	contractor c		
CALLER REI the driver f they think v pump out t	MARKS: forgot to unhoc went down into the storm drain	ok the hose from the othe storm drain, so l. CLAS aterial Other	me of the spill	and it spilled has been d SPILLED 50.00 G	l out about 50 g cleaned out. the RECO 0.00 C	y have a	contractor c	oming to	
CALLER REI the driver f they think v pump out t	MARKS: forgot to unhoo went down into the storm drain	ok the hose from the othe storm drain, so l. CLAS aterial Other	me of the spill	and it spilled has been d SPILLED 50.00 G	l out about 50 g cleaned out. the RECO 0.00 C	VERED	contractor c	ES AFFECTED	
the driver f they think v pump out t MATERIAL unknown non-pe	MARKS: forgot to unhoo went down into the storm drain	ok the hose from the of the storm drain, so it. CLAS aterial Other ADDRESS	me of the spill	and it spilled has been d SPILLED 50.00 G	l out about 50 g cleaned out. the RECO 0.00 C	VERED CON DAV	RESOURC Soil,	ES AFFECTED	
the driver f they think v pump out t MATERIAL unknown non-pe	MARKS: forgot to unhoo went down into the storm drain stro/non-haz ma	ok the hose from the othe storm drain. so it. CLAS aterial Other ADDRESS ALBANY N	Me of the spill	and it spilled has been d SPILLED 50.00 G	l out about 50 g cleaned out. the RECO 0.00 C	CON DAV	RESOURC Soil, TACT E CARABET	ES AFFECTED	
the driver f they think v pump out t MATERIAL unknown non-pe COMPANY UNITED OIL(NO	MARKS: forgot to unhood went down into the storm drain etro/non-haz ma ORLITE)	ok the hose from the othe storm drain. so it. CLAS aterial Other ADDRESS ALBANY N	Me of the spill	spilled SPILLED 50.00 G	RECO 0.00 C	CON DAV	RESOURC Soil, TACT E CARABET	ES AFFECTED	
CALLER REI the driver f they think is pump out t MATERIAL unknown non-pe COMPANY UNITED OIL(NO Tank No. Tank DEC REMAR	MARKS: forgot to unhoo went down into the storm drain etro/non-haz ma DRLITE) Size Materia RKS: 04 data transla	ok the hose from the of the storm drain, so it. CLAS aterial Other ADDRESS ALBANY No. Cause	me of the spill SS POTENTIAL NY Sc	SPILLED 50.00 G SPILLEI	RECO 0.00 C	CON DAV	RESOURC Soil, TACT E CARABET	ES AFFECTED	

CLASS: C3 CLOSE DATE: 03/08/2004 MEETS STANDARDS: False

T & A

Created On: 03/03/2004 FOIL195989

Date Printed: 12/12/2018 Last Updated: 03/08/2004 15

COST CENTER





DEC REGIO		INEDT EASILI	D.(SPILL NU		0314		
SPILL NAM	/IE: <u>H1</u>	INERT FACILI	I Y		DEC LEA	AD:	CFM/	ANNES	
CALLER NA	AME:	KEVIN CARTNE	R		NOTIFIER	R'S NAME:	KEVIN	CARTNER	
CLR'S AGE	ENCY:	NEW VENTURE	GEAR		NOTIFIER	R'S AGENCY:	NEW V	ENTURE GE	AR
CALLER'S	PHONE:	(315) 432-4036			NOTIFIER	R'S PHONE:	(315) 4	32-4036	
SPILL DAT	TE:	03/2	24/2004	SPILL T	IME:	11:00 am		DISPATCH	IER:
CALL REC	EIVED D	O3/2	24/2004	RECEIV	ED TIME:	11:27 am			
			SF	PILL LOC	ATION				
PLACE:	H1 IN	NERT FACILITY			COUN.	TY:	Onond	aga	
STREET:	6600	NEW VENTUR	E GEAR RD		TOWN	/CITY:	***** U	nknown *****	
					COMM	UNITY:	EAST S	SYRACUSE	
CONTAC	T: <u>PHI</u>	LLIS PRINCE			CONT	ACT PHONE:	(315)	438-2716	
CONT. FAC	CTOR:	Unknown			SPILL	REPORTED E	Y : Other	r	
FACILITY TYPE: Unknown				WATE	RBODY:				
	y discove	red impacted so	il underneath co available today, (
MATERIAL unknown peti	roleum		CLASS Petroleur		SPILLED 0.00 L	RECO 0.00 L		RESOURC GW,	ES AFFECTED
			<u>PO1</u>	ΓENTIAL	SPILLER	RS			
COMPANY H1 INERT F	ACILITY	=	ADDRESS 6600 NEW VENT	URE GEAI	R RD EAS	ST SYRACUSI	E N PHI	NTACT LLIS PRINCE 5) 438-2716	≣
Tank No. T	ank Size	Material	Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REM	MARKS:								
Prior to Sept	, 2004 da	ta translation thi	s spill Lead_DE0	C Field was	"CM"				
<u>PIN</u>		<u>T & A</u>		COST C	<u>ENTER</u>				
CLASS: (C3	CLOSE DATE	: 05/04/2004		MEETS ST	ANDARDS:	False		

Created On: 03/24/2004 FOIL195990

Date Printed: 12/12/2018 Last Updated: 05/05/2004 16





DEC REGION: SPILL NAME:	7 .E DOCK S1	ORM DRAIN		SPILL NU		03142 CFMA	282 ANNES	
CALLER NAME CLR'S AGENCY CALLER'S PHO	E: PHYLIS F	PRINCE NTURE GEAR		NOTIFIEF NOTIFIEF	R'S NAME: R'S AGENCY: R'S PHONE:	PHYLIS NEW VI	PRINCE ENTURE GE	AR
SPILL DATE: CALL RECEIV		03/30/2004 03/30/2004	SPILL T		5:00 pm 6:38 pm		DISPATCH	IER:
			SPILL LOC	ATION				
PLACE: STREET:	.E DOCK STO	•	SFILL LOC	COUN' TOWN		Ononda	aga nknown *****	
0111=11				_	UNITY:		SYRACUSE	
CONTACT:	PHYLIS PRIN	ICE		CONT	ACT PHONE:	(315)	438-2716	
CONT. FACTO	R: Other			SPILL	REPORTED E	Y : Other		
FACILITY TYPE: Commercial/Industrial				-	RBODY:	1, 3, 3, 3, 3		
CALLER REI	_	/aste management t	o repair the di	rum. and a	contractor was	called to	clean out th	e storm drain
MATERIAL hydraulic oil		CLAS Petrole		SPILLED 25.00 G	RECO 0.00 (VERED	RESOURC Soil,	ES AFFECTED
		<u>P</u> (OTENTIAL	SPILLER	<u>ks</u>			
COMPANY .E DOCK STOR	M DRAIN	ADDRESS 6600 NEW VE	NTURE GEA	R RD EAS	ST SYRACUSI		ITACT 'LIS PRINCE	:
						(315	5) 438-2716	
Tank No. Tank	Size Material	Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR	KS:							
Prior to Sept, 200	04 data translat	tion this spill Lead_D	DEC Field was	s "CM"				
PIN	<u>T</u>	<u>& A</u>	COST C	ENTER				
CLASS: C3	CLOSE	DATE: 04/02/200	4	MEETS ST	ANDARDS:	False		

Created On: 03/30/2004 FOIL195991

Date Printed: 12/12/2018 Last Updated: 04/02/2004 17





DEC REGION:	1 : _7			SPILL NU	IMBER:	0403142		
SPILL NAME:	NEW VENT	URE GEAR		DEC LEA	D:	HDW	ARNER	
CALLER NAME	: PHYLIS I	PRINCE	N	OTIFIER	R'S NAME:	PHYLIS	PRINCE	
CLR'S AGENC	Y: NEW VE	NTURE GEAR	N	OTIFIER	R'S AGENCY:	NEW VE	ENTURE GE	AR
CALLER'S PHO	ONE: (315) 438	3-2716	N	OTIFIER	R'S PHONE:	(315) 43	8-2716	
SPILL DATE:		06/22/2004	SPILL TIM	E: _	12:30 pm		DISPATCH	IER:
CALL RECEIV	ED DATE:	06/22/2004	RECEIVED	TIME:	1:36 pm			
		SP	ILL LOCA	TION				
PLACE:	NEW VENTU	RE GEAR		COUNT	ΓY:	Ononda	ıga	
STREET:	6600 NEW VE	ENTURE GEAR RD		TOWN/	CITY:		known *****	
				СОММ	UNITY:	DEWITT		
CONTACT:	PHYLIS PRII	NCE		CONTA	ACT PHONE:	(315) 4	38-2716	
CONT. FACTOR: Unknown SPILL REPORTED BY: Other FACILITY TYPE: Institutional, Educational, Gov., Othe WATERBODY:								
THE SEAM	ONTAMINATE 1 OF TEH CON	D SOIL WITH A PETRO NCRETE APPEARED TO CONSTRUCTION						
MATERIAL unknown petrolei	ım	CLASS Petroleum	_	PILLED .00 L	RECO 0.00 L	VERED	RESOURC Soil,	ES AFFECTED
		POT	ENTIAL S	PILLER	<u>.s</u>			
COMPANY NEW VENTURE	GEAR	ADDRESS 6600 NEW VENTU	JRE GEAR F	RD DEV	WITT NY	PHY	I TACT LIS PRINCE) 438-2716	<u> </u>
Tank No. Tank	Size Materia	I Cause	Source	ce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR	KS:							
Prior to Sent 200	n4 data transla	tion this snill Lead DEC	Field was "F	- 1\ Λ/ "				

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "HW' see spill # 0404337

PIN T&A COST CENTER

CLASS: D4 CLOSE DATE: 09/21/2004 MEETS STANDARDS: False

Created On: 06/22/2004 FOIL195992

Date Printed: 12/12/2018 Last Updated: 09/21/2004 18





DEC REGION: SPILL NAME:	-	URE GEAR		SPILL NU		04034 BFMA	181 ATTHE	
CALLER NAME CLR'S AGENC' CALLER'S PHO	Y: NEW VEI	NTURE GEAR			'S NAME: 'S AGENCY: 'S PHONE:	NEW VI		AR
SPILL DATE: CALL RECEIV	ED DATE:	07/01/2004 07/01/2004	SPILL TI	ME: _	5:00 am 7:53 am		DISPATCH	ER:
			SPILL LOC	ATION				
PLACE:	NEW VENTU	RE GEAR	<u> </u>	COUNT	Υ:	Ononda	aga	
STREET:	6600 NEW VE	ENTURE GEAR RE)	TOWN/	CITY:	***** Ur	nknown *****	
				COMM	JNITY:	EAST S	SYRACUSE	
CONTACT:	PHYLIS PRIN	NCE		CONTA	CT PHONE:	(315)	138-2716	
CONT. FACTO	R: Other	r		SPILL I	REPORTED B	Y: Resp	onsible Party	
FACILITY TY	PE: Unkn	own		WATER	RBODY:			
CALLER REI STILL INVI	_	UNSURE HOW IT	HAPPENED: Cl	EAN UP C	ONTRACTOR	ON SCE	ENE	
MATERIAL hydraulic oil		CLA Petro	ASS oleum	SPILLED 0.00 L	RECO 0.00 L	VERED	RESOURC Soil,	ES AFFECTED
			POTENTIAL	SPILLER	S			
COMPANY NEW VENTURE	E GEAR	ADDRESS	'ENTURE GEAF		<u>-</u> VITT NY	PHY	ITACT 'LIS PRINCE ') 438-2716	
Tank No. Tank	Size Materia	l Cause	e Sou	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 200 referred to water	04 data transla	ition this spill Lead	_DEC Field was	"BM"				
PIN	1	Г& А	COST CI	ENTER				
CLASS: C3	CLOSE	DATE: 07/16/20	004	MEETS ST	ANDARDS:	False		

Created On: 07/01/2004 FOIL195993

Date Printed: 12/12/2018 Last Updated: 07/16/2004 19



C4

NYSDEC SPILL REPORT FORM



DEC REGION: SPILL NAME:				SPILL NUMBER: DEC LEAD:		0404337 HDWARNER		
CALLER NAME CLR'S AGENC' CALLER'S PHO	Y: NEW VEN	TURE GEAR		NOTIFIER	R'S NAME: R'S AGENCY: R'S PHONE:	NEW VI		AR
SPILL DATE: CALL RECEIV	ED DATE:	07/22/2004 07/22/2004	SPILL TI		1:30 pm 2:03 pm		DISPATCH	ER:
PLACE: STREET: CONTACT:	SOUTH DOCK 6600 NEW VEI	NTURE GEAR DRIVE	ILL LOC	COMM	/CITY: IUNITY:		aga SYRACUSE 438-2716	
CONT. FACTOR: Other SPILL REPORTED BY: Responsible Party FACILITY TYPE: Unknown WATERBODY:								
	RED DURING D	OIGGING SIX FEET IN TO NOT KNOWN. UNDER			HE CONCRET	E WALL	THERE IS O	IL LEAKING
MATERIAL other -		CLASS Other		SPILLED 0.00 L	RECO 0.00 L	VERED	RESOURC Soil,	ES AFFECTED
COMPANY SOUTH DOCK		POTI ADDRESS 6600 NEW VENTU		SPILLER	_	E PHY	ITACT 'LIS PRINCE) 438-2716	
ank No. Tank	Size Material	Cause	Sou	ırce	Test Meth	od	Leak Rate	Gross Failure
9-20-2004: Site i	04 data translat nspection met v be a result of m	on this spill Lead_DEC vith Phylis Prince @ Ne inor spills from plant op	w Venture	. Minor co	ntamination fo	und arou	nd footer. It	

CLOSE DATE: 02/07/2007

Created On: 07/22/2004 FOIL195994

Date Printed: 12/12/2018 Last Updated: 02/07/2007 20

False

MEETS STANDARDS:





DEC REGION: SPILL NAME:	7 MANUFAC	7 MANUFACTURING FACILITY			JMBER:	04086 CXR0	
	ALLER NAME: PHYILLIS PRINCE LR'S AGENCY: NEW PROCESS GEAR ALLER'S PHONE: (315) 438-2716			NOTIFIER'S NAME: NOTIFIER'S AGENCY: NOTIFIER'S PHONE:		NEW PI	
SPILL DATE: CALL RECEIV	ED DATE:	11/05/2004 11/05/2004	SPILL TI	IME: ED TIME:	10:30 am 4:36 pm		DISPATCHER:
PLACE: STREET: CONTACT:		RING FACILITY ENTURE DRIVE	PILL LOC	COMM		EAST S	aga nknown ***** SYRACUSE 438-2716
CONT. FACTO		nercial/Industrial			REPORTED I		onsible Party ES OUTFALL
FIRE. AFT	E WAS WELDI ER THE FIRE UM BASED OI	WAS PUT OUT AT AP	PROX. 3:3	0 THIS AF	TERNOON, T	HE CALL	JLATION AND CAUSED A ER FOUND THE ILY CHIPS. WENT INTO
MATERIAL other -		CLASS Other		SPILLED	REC (0.00 (OVERED G	RESOURCES AFFECTED Soil,
		РОТ	ENTIAL	SPILLER	RS		_
COMPANY		ADDRESS				CON	NTACT

MANUFACTURING FACILITY 6600 NEW VENTURE DRIVE EAST SYRACUSE NY PHYLLIS PRINCE

(315) 438-2716

Tank No. Tank Size Material Cause Source **Test Method** Leak Rate Gross Failure

DEC REMARKS:

Fire in crusher room. Water used to fight fire between wall also flushes oil on floor and in hopper, into near by storm drain and out to SPDES outfall. Oil was predominately soluable oil. Inspection of discharge to pond revealed only small amount of cloudyness in water column.

PIN T & A **COST CENTER**

CLASS: **CLOSE DATE:** 11/08/2004 **MEETS STANDARDS:** True

11/05/2004 Created On: FOIL195995 Date Printed: 12/12/2018 Last Updated: 11/08/2004 21



D4

CLOSE DATE: 12/21/2004

NYSDEC SPILL REPORT FORM



DEC REGION: SPILL NAME:	7 6600 NEW VE	NTURE GEAR DRIVE	≣	SPILL NU		04095 CXRC		
CALLER NAME CLR'S AGENC' CALLER'S PHO		CESS GEAR		NOTIFIER	R'S NAME: R'S AGENCY: R'S PHONE:	NEW PF		:AR
SPILL DATE: CALL RECEIV	ED DATE:	11/24/2004 11/24/2004	SPILL TI	ME: ED TIME:	2:04 pm 3:01 pm		DISPATCH	IER:
PLACE: STREET: CONTACT:		TURE GEAR DRIVE	ILL LOC	COMM		EAST S	aga aknown **** SYRACUSE 138-2716	
CONT. FACTO		rcial Vehicle			REPORTED B RBODY:	Y: Feder	al Governme	ent
CALLER REM no commen	_							
MATERIAL diesel		CLASS Petroleum		SPILLED 5.00 G	RECO 5.00 G	VERED	RESOURC Soil,	ES AFFECTED
COMPANY UNKNOWN		POTI ADDRESS 6600 NEW VENTU		SPILLER R DRI EA	_	E PHY	ITACT 'LISS PRINC) 438-2716	Έ
Гаnk No. Tank	Size Material	Cause	Soi	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR	KS:							
PIN	T 8	. А	COST CI	<u>ENTER</u>				

11/24/2004 Created On: FOIL195996

Last Updated: 12/21/2004 22 Date Printed: 12/12/2018

MEETS STANDARDS:

True





DEC REGION:						SPILL NI	UMBER:	05029	938	
SPILL NAME:	NE\	N PROCE	ESS GEA	AR .		DEC LEA	AD:	BFMA	ATTHE	
CALLER NAM	E :P	HILLIS PI	RINCE			NOTIFIE	R'S NAME:	PHILLIS	PRINCE	
CLR'S AGENC	Y:N	IEW PRO	CESS G	SEAR		NOTIFIE	R'S AGENCY:	NEW P	ROCESS GE	AR
CALLER'S PH	ONE <u>: (</u> 3	315) 438-2	2716			NOTIFIE	R'S PHONE:	(315) 43	38-2716	
SPILL DATE:		_	06/10/2	2005	_ SPILL T	IME:	3:30 pm		DISPATCH	IER:
CALL RECEIV	VED DA	ATE:	06/10/2	2005	RECEIV	ED TIME:	5:02 pm			
				SI	PILL LOC	ATION				
PLACE:	NEW	PROCES	S GEAR	<u> </u>		COUN	TY:	Ononda	aga	
STREET:	6600	NEW VEN	TURE (GEAR RD		TOWN		Dewitt		
						-	IUNITY:		SYRACUSE	
CONTACT:	PHIL	LIS PRIN	CE			CONT	ACT PHONE:	(315)	438-2716	
CONT. FACTO	DR:	Other				SPILL	REPORTED E	Y: Resp	onsible Party	,
FACILITY TY	YPE:	Instituti	ional, Ed	ducational, Go	ov., Othe	WATE	RBODY:	STOF	RM WATER I	POND
	AL ANI	D HAS BE					H RAIN THE C SOME WENT			
MATERIAL lube oil				CLASS Petroleui	m	SPILLED 1.00 G	RECO 1.00 (RESOURC SW,	ES AFFECTED
				<u>PO</u>	TENTIAL	SPILLER	<u>RS</u>			
COMPANY NEW PROCES	S GEAI	₹		DRESS 0 NEW VENT	ΓURE GEA	R RD EA	ST SYRACUSI	E N PHII	NTACT LLIS PRINCE 5) 438-2716	≣
Tank No. Tank	< Size	Material		Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAF	RKS:									
<u>PIN</u>		<u>T</u> (<u>& A</u>		COST C	ENTER				
CLASS: C4		CLOSE E	DATE:	06/27/2005		MEETS ST	TANDARDS:	True		

Created On: 06/10/2005

Date Printed: 12/12/2018

Last Updated: 06/27/2005

FOIL195997

23





DEC REGION:	7			SPILL N	UMBER:	05044	85	
SPILL NAME:	MAGNA DRIVE	TRAIN STORMWAT	ER PONE	DEC LEA	AD:	KCKe	mp	
CALLER NAME:	KEVIN CART	NER		NOTIFIE	R'S NAME:	KEVIN (CARTNER	
CLR'S AGENCY	: NEW PROCE	SS GEAR		NOTIFIE	R'S AGENCY:	NEW P	ROCESS GE	AR
CALLER'S PHO	NE: (315) 432-403	36		NOTIFIE	R'S PHONE:	(315) 43	2-4036	
SPILL DATE:	07	7/14/2005	SPILL TI	ME:	4:00 pm		DISPATCH	ER:
CALL RECEIVE	D DATE: 07	7/14/2005	RECEIVE	ED TIME:	6:55 pm			
		SPI	ILL LOC	<u>ATION</u>				
PLACE:	MAGNA DRIVETR	AIN STORMWATE	R POND	COUN	TY:	Ononda	iga	
STREET: 6	600 NEW VENTU	JRE GEAR RD			I/CITY:	Dewitt		
-				•	IUNITY:		SYRACUSE	
CONTACT: _	KEVIN CARTNEF	₹		CONT	ACT PHONE:	(315) 4	132-4036	
CONT. FACTOR	: Other			SPILL	REPORTED B	Y: Respo	onsible Party	
FACILITY TYP	E: Commerc	ial/Industrial		WATE	RBODY:	SAND	ERS CREEK	<
CALLER REMA	ARKS: Ill, overflow of coll	ection pond.						
//ATERIAL		CLASS	;	SPILLED	RECO	VERED	RESOURC	ES AFFECTED
ınknown petroleur	m	Petroleum			0.00 G	}	SW,	
		<u>POTI</u>	ENTIAL	SPILLEF	<u>RS</u>			
COMPANY		ADDRESS 6600 NEW VENTU	JRE GEAF	RRD EA	ST SYRACUSE	_	ITACT IN CARTNEI	२
						(315) 432-4036	
ank No. Tank S	Size Material	Cause	Sou	ırce	Test Meth	od	Leak Rate	Gross Failure
DEC REMARK	S:							
noted on surface o	during site visit 7/1	or overflowed during 5 AM. Oil / Sheen i contract Op-tech di	near pond	discharge	noted as being	controle	d with severa	
DIN	т о л		COST CE	NTED				

PIN T & A COST CENTER

CLASS: C3 CLOSE DATE: 07/15/2005 MEETS STANDARDS: True

Created On: 07/14/2005

Date Printed: 12/12/2018

Last Updated: 07/15/2005

FOIL195998

24





DEC REGION:	N: <u>7</u>			SPILL NU	MBER:	0508308		
SPILL NAME:	NEW PROCES	S GEAR		DEC LEA	D:	KCKemp		
CALLER NAME:	PHYLLIS PR	INCE		NOTIFIER	'S NAME:	PHYLLIS PRINCE		
CLR'S AGENCY	: NEW PROC	ESS GEAR		NOTIFIER	'S AGENCY:	NEW PROCESS O	EAR	
CALLER'S PHONE: (315) 438-2716				NOTIFIER	'S PHONE:	(315) 438-2716		
SPILL DATE:	1	0/12/2005	SPILL TI	ME:	9:30 am	DISPATO	HER:	
CALL RECEIVE	D DATE:1	0/12/2005	RECEIVI	ED TIME:	10:24 am			
		SF	PILL LOC	ATION				
PLACE:	NEW PROCESS			COUNT	Υ:	Onondaga		
STREET:	600 NEW VENT	URE GEAR RD		TOWN/		Dewitt		
-				COMM	JNITY:	DEWITT		
CONTACT:	CONTACT: PHYLLIS PRINCE				CT PHONE:	(315) 546-5785	CELL	
CONT. FACTOR	R: Unknowr	1		SPILL I	REPORTED B	Y: Other		
FACILITY TYP	PE: Institution	nal, Educational, Go	v., Othe		RBODY:	STORM WATER	LAGOON	
CALLER REM 6% OIL AND		INVESTIGATING:						
MATERIAL cutting oil		CLASS Petroleur		SPILLED	RECO 0.00 G		CES AFFECTED	
		<u>PO1</u>	TENTIAL	SPILLER	<u>s</u>			
COMPANY NEW PROCESS	GEAR	ADDRESS 6600 NEW VENT	URE GEAF	RRD DEV	VITT NY	CONTACT PHYLLIS PRIN (315) 546-5785		
Tank No. Tank S	Size Material	Cause	Soi	urce	Test Meth	od Leak Rate	e Gross Failure	
DEC REMARK	(S:							

10/12/2005 Created On:

C3

source eliminated.

PIN

CLASS:

FOIL195999 Last Updated: 11/30/2005 Date Printed: 12/12/2018 25

COST CENTER

MEETS STANDARDS:

False

Leak traced heat transfer fluid / cutting oil at Dept. 580 / LaSalle area. Cores taken by OB&G in area of leak and

11/30/2005 - Received written status report from Phyllis Prince at Magna Drivetrain.

T & A

CLOSE DATE: 11/30/2005





DEC REGION:	7			SPILL NU	JMBER:	0511678			
SPILL NAME:	NEW PROCES	S GEAR		DEC LEA		KACAHILL			
CALLER NAME	: PHYLLIS PR	INCE		NOTIFIE	R'S NAME:	PHYLLIS PRINCE			
CLR'S AGENC	Y: NEW PROC	ESS GEAR		NOTIFIE	R'S AGENCY:	NEW PROCESS (GEAR		
CALLER'S PHO	ONE: (315) 438-27	16		NOTIFIE	R'S PHONE:	(315) 438-2716			
SPILL DATE:	_ (1/10/2006	SPILL T	IME:	11:00 am	DISPATO	CHER:		
CALL RECEIV	ED DATE:	01/10/2006	RECEIV	ED TIME:	11:29 am				
SPILL LOCATION									
PLACE:	NEW PROCESS	GEAR		COUN	TY:	Onondaga			
STREET:	6600 NEW VENT	URE GEAR RD		TOWN	/CITY:	Dewitt			
				COMM	IUNITY:	DEWITT			
CONTACT:	PHYLLIS PRINC	E		CONT	ACT PHONE:	(315) 546-5785	CELL		
CONT. FACTOR: Other SPILL REPORTED BY: Other									
FACILITY TY	PE: Institution	nal, Educational, Go	v., Othe	WATERBODY:					
CALLER REM DURING C		FOUND CONTAMIN	IATED SO	IL WITH G	ASOLINE:				
MATERIAL diesel		CLASS Petroleun	n	SPILLED 2.00 G	RECO 2.00 G		CES AFFECTED		
		<u> POT</u>	ENTIAL	SPILLER	RS				
COMPANY NEW PROCESS	S GEAR	ADDRESS 6600 NEW VENT	URE GEA	R RD DE'	WITT NY	CONTACT PHYLLIS PRIN			
						(315) 546-578	5 CELL		
Tank No. Tank	Size Material	Cause	So	urce	Test Meth	od Leak Rat	e Gross Failure		

DEC REMARKS:

01-10-06 Contaminated soil encountered below 2 dyno machines that were removed this winter from a room inside the plant. Each machine had a drain and the affected soil is proximate to those drains. One was powered with gasoline and other with diesel. They have dug out soil around sump pipes. PID readings low near gas machine sump. In 100s near other sump. Engineer is concerned with hitting clay pipes located approx. 1 foot below dug out area. Instructed them to dig out area near diesel machine sump as much as possible, record PID readings and then collect sammples. They will get 24 hour TAT.

01-13-06 Received data from confirmation samples. Closed spill.

PIN T & A COST CENTER

Created On: 01/10/2006 FOIL196000

Date Printed: 12/12/2018 Last Updated: 01/30/2006 26





 DEC REGION:
 7
 SPILL NUMBER:
 0511678

SPILL NAME: NEW PROCESS GEAR DEC LEAD: KACAHILL

CLASS: D3 CLOSE DATE: 01/13/2006 MEETS STANDARDS: True

Created On: 01/10/2006 FOIL196001

Date Printed: 12/12/2018 Last Updated: 01/30/2006 27





DEC REGION:	7	7			UMBER:	0600458			
SPILL NAME:	NEW PRO	CESS GEAR		DEC LEA	AD:	KACAHILL			
CALLER NAME	ER NAME: PHYLLIS PRINCE			NOTIFIEI	R'S NAME:	PHYLLIS PRINCE			
CLR'S AGENCY	: NEW PROCESS GEAR			NOTIFIE	R'S AGENCY:	NEW PROCESS GEAR			
CALLER'S PHONE: (315) 438-2716			NOTIFIE	R'S PHONE:	(315) 438-2716				
SPILL DATE:		04/12/2006	SPILL TI	ME:	10:00 am	DISPATCHER:			
CALL RECEIVED DATE: 04/12/2006 RECEIVE			ED TIME:	10:40 am					
SPILL LOCATION									
PLACE:	NEW PROCE	SS GEAR		COUN	TY:	Onondaga			
STREET:	6600 NEW VE	ENTURE GEAR RD		TOWN	I/CITY:	Dewitt			
				COMM	IUNITY:	EAST SYRACUSE			
CONTACT:	PHYLLIS PR	INCE		CONT	ACT PHONE:	(315) 546-5785 CELL			
CONT. FACTO	R: Othe	r		SPILL	REPORTED B	Y: Other			
FACILITY TYPE: Institutional, Educational, Gov., Othe			WATERBODY:						
	CALLER REMARKS: DURING CONSTRUCTION DUE TO WATER MAIN RREAK FOUND CONTAMINATED SOU								

MATERIAL CLASS RECOVERED RESOURCES AFFECTED SPILLED cutting oil Petroleum 0.00 G Soil.

POTENTIAL SPILLERS

COMPANY ADDRESS CONTACT

DAIMLERCHRYSLER CORP 800 CHRYSLER DRIVE AUBURN MILLS MI 48326-2 L. ALAN JOHNSTON

(248) 576-7357

Tank No. Tank Size Material Cause Source **Test Method** Leak Rate Gross Failure

DEC REMARKS:

Spoke to Phyllis. They were doing a water line repair and encountered comtaminated soil. This is related to an old spill called in regarding same area. Spill #0308123. Contamination encountered under the East Pad. Pad used to rinse equipment and drums that store petroleum products, mostly cutting fluids. The pad has cracks and over the years, rinsate has contaminated the soil below the pad. Spoke to Regional Engineer and he wants a STIP in place to put them on a schedule. Phyllis indicated that Daimler Chrysler still owns this property.

STIP mailed to Phyllis's attention on 4/13/06.

05/17/06 Al Johnston with Daimler Chrysler (DC) contacted me. They have the analytical data back from the water line repair sampling and he will email to me. Al indicated that DC is reluctant to sign the STIP.

05/23/06 Conducted site visit with Phyllis Prince (NVG), Tom Sullivan (NVG), and Al Johnson. I will seek input from DRB, MJP, and enforcement.

04/12/2006 Created On: FOIL196002 Date Printed: 12/12/2018 Last Updated: 12/07/2007 28





DEC REGION:	_ 7	SPILL NUMBER:	0600458
SPILL NAME:	NEW PROCESS GEAR	DEC LEAD:	KACAHILL

05/30/06 Discussed situation with DEC enforcement. No apparent violations with the process. Dicussed with DRB, and he wants DC to install at least 3 groundwater monitoring wells at edge of pad to determine if groundwater has been affected. If so, STIP or CO will have to be signed by DC. If groundwater is not affected, then DEC will require that pad be cleaned and cracks be sealed. Contacted Phyllis and she would like to have something in writing from DEC regarding repair of the pad.

06/2/06 LVM for Al Johnson.

06/06/06 Al called me back. He will send a letter proposal for well installation and cleaning/sealing of the pad.

06/23/06 Received and approved proposal. Four borings/monitoring wells to be installed.

07/27/06 Concrete repair activities completed on East Pad.

09/12/06 Al contacted me. Fieldwork scheduled for 9/14.

09/14/06 DC installed four soil borings but no wells were installed as no water was encountered. M. Romocki onsite.

12/27/06 Met Tammy Raby with Earth Tech and Emery with NVG. Earth Tech had planned to sampled the four wells, but none had J-plugs in them, so sampling will be pushed off. Instructed Tammy to re-purge the wells and then plug.

01/12/07 Earth Tech sampled wells.

04/19/07 Received Investigation report from DC.

05/07/07 Tom Sullivan contacted me and indicated that the pad has been pressure washed.

07/12/07 Requested that DC resample MW-1 due to questionable data qualifier.

08/28/07 MW-1 resampled.

12/3/07 Received final investigation report from DC.

04/12/2006

PIN **T & A COST CENTER**

C3 **CLOSE DATE:** 12/07/2007 **CLASS: MEETS STANDARDS:** False

Created On: FOIL196003 Date Printed: 12/12/2018 Last Updated: 12/07/2007 29



D4

CLOSE DATE: 10/18/2006

NYSDEC SPILL REPORT FORM



DEC REGION: SPILL NAME:	7 NEW PROCESS 0	GEAR		SPILL NUM		06077 HDW	700 ARNER	
CALLER NAME CLR'S AGENC' CALLER'S PHO			<u> </u>		S NAME: S AGENCY: S PHONE:	NEW PF		AR
SPILL DATE: CALL RECEIV		_	SPILL TIM	_	8:00 am 8:16 am		DISPATCH	IER:
PLACE: STREET: CONTACT:	NEW PROCESS GE 6600 NEW VENTUR PHYLLIS PRINCE	AR	L LOCA	COUNTY TOWN/C	ITY:			≣LL
CONT. FACTO	1 66 6 1	Othe	SPILL REPORTED BY: Other WATERBODY:					
CALLER REM SPINNER I MATERIAL cutting oil	MARKS: MALFUNCTIONED, (CAUSING OIL TO S CLASS Petroleum	SI	RAILROAD PILLED 0.00 G		VERED		ANING UP:
COMPANY NEW PROCESS		POTE ADDRESS 600 NEW VENTUR		PILLERS		N PHY	ITACT LLIS PRINC) 546-5785	E CELL
Гаnk No. Tank	Size Material	Cause	Sour	ce	Test Metho	od	Leak Rate	Gross Failure
DEC REMAR	KS:							
PIN	T & A	(COST CEN	<u>ITER</u>				

Created On: 10/06/2006 FOIL196004

Date Printed: 12/12/2018 Last Updated: 12/11/2006 30

MEETS STANDARDS:

False





DEC REGION:	7			SPILL N	UMBER:	06108	376			
SPILL NAME:	NEW PROCESS	S GEAR		DEC LE	AD:	KACA	AHILL			
CALLER NAME:	: PHYLLIS PRI	NCE		NOTIFIE	R'S NAME:	PHYLLI	S PRINCE			
CLR'S AGENCY	: NEW PROCE	SS GEAR		NOTIFIE	R'S AGENCY:	NEW P	ROCESS GE	AR		
CALLER'S PHO	NE: (315) 438-27	16		NOTIFIE	R'S PHONE:	(315) 43	38-2716			
SPILL DATE:	1:	2/27/2006	SPILL TI	ME:	12:00 pm		DISPATCH	IER:		
CALL RECEIVE	ED DATE: 1	2/27/2006	RECEIVE	ED TIME:	2:28 pm					
SPILL LOCATION										
PLACE:	NEW PROCESS (GEAR		COUN	NTY:	Ononda	aga			
STREET:	6600 NEW VENTU	JRE GEAR DRIVE		TOW	N/CITY:	Dewitt				
-				СОМІ	MUNITY:	EAST S	SYRACUSE			
CONTACT:	PHYLLIS PRINCI	E		CONT	TACT PHONE:	(315)	546-5785 CE	ELL		
CONT. FACTOR: Unknown SPILL REPORTED BY: Local Agency										
FACILITY TYP	E: Unknown			WATE	ERBODY:					
	CAVATION AT T	HIS LOCATION, CO E BUILDING AND IS			L WAS DISCO\	/ERED:	MATERIAL \	WAS		
MATERIAL cutting oil		CLASS Petroleum		SPILLED	RECO 0.00 (VERED	RESOURC Soil,	ES AFFECTED		
		POT	ENTIAL	SPILLE	RS					
COMPANY DAIMLERCHRYS	SLER CORP	ADDRESS 800 CHRYSLER D	DRIVE A	UBURN M	1ILLS MI 4832	6-2 L. A	NTACT LAN JOHNS 3) 576-7357	TON		
Tank No. Tank S	Size Material	Cause	Sou	ırce	Test Meth	od	Leak Rate	Gross Failure		
DEC REMARK	(S:									
placing in rolloffs.	Clay layer below	d Daimler Chrysler. that appears to be of historical use of the	clean. The	y will colle	ect confirmation	samples	and send to	lab.		

01/02/07 Al Johnson, Daimler, contacted me. The soil has been scaped up and 6 confirmation samples collected. The room was used for storage according to his records. I instructed him to have samples run for STARS 8260/8270.

03/22/07 Received soil disposal receipt. Closed spill.

PIN T & A COST CENTER

12/27/2006 Created On: FOIL196005 Last Updated: 04/04/2007 Date Printed: 12/12/2018 31





 DEC REGION:
 7
 SPILL NUMBER:
 0610876

SPILL NAME: NEW PROCESS GEAR DEC LEAD: KACAHILL

CLASS: D4 CLOSE DATE: 04/02/2007 MEETS STANDARDS: True

Created On: 12/27/2006 FOIL196006

Date Printed: 12/12/2018 Last Updated: 04/04/2007 32





DEC REGION: SPILL NAME:		TENTION PC	ND		SPILL NU		07002 cxros		
CALLER NAME CLR'S AGENC' CALLER'S PHO	Y:(DISPATCHER DNONDAGA (315) 435-888	FIRE		NOTIFIER	R'S NAME: R'S AGENCY: R'S PHONE:	ONONE		
SPILL DATE: CALL RECEIV	ED D		l/10/2007 l/10/2007	SPILL T	IME: ED TIME:	7:19 am 7:19 am		DISPATCH	IER:
			S	PILL LOC	ATION				
PLACE:					COUNTY: Onondaga				
STREET:	6600	ONONDAGA	LAKE PKWY		TOWN	/CITY: IUNITY:	Salina SALINA		
CONTACT:	FIRE	E CHIEF- JOH	IN MULDOON		_	ACT PHONE:		243-7832	
CONT. FACTOR: Other SPILL REPORTED BY: Fire Department									
FACILITY TYPE: Passenger Vehicle				-	RBODY:	1102	- oparamona		
CALLER REI			T WANTED TO N	OTIFY DEC):				
MATERIAL unknown petrolei	um		CLASS Petroleu	m	SPILLED 0.00 G	RECO 0.00 (VERED	RESOURC SW,	ES AFFECTED
			<u>PO</u>	TENTIAL	SPILLER	RS			
COMPANY PASSENGER V	ÆHICI	LE	ADDRESS NY				CON	ITACT	
Tank No. Tank	Size	Material	Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR	KS:								
PIN		<u>T & A</u>	1	COST C	ENTER				
CLASS: F6		CLOSE DAT	r E : 04/17/2007		MEETS ST	ANDARDS:	True		

Created On: 04/10/2007

Date Printed: 12/12/2018

Last Updated: 04/17/2007

50|L196007 | 33|





DEC REGION: SPILL NAME:	7 NEW PROCE	ESS GEAR		SPILL NU		0701912 kacahill		
CALLER NAME CLR'S AGENCY CALLER'S PHO				NOTIFIER'S NAME: NOTIFIER'S AGENCY: NOTIFIER'S PHONE:		JAMES BROWN NEW PROCESS GEAR (315) 431-7089		EAR
SPILL DATE: CALL RECEIV	ED DATE:	05/16/2007 05/16/2007	SPILL TIN	•	11:00 am 12:17 pm		DISPATCH	IER:
. 2, (02.	NEW PROCES 6600 NEW VEN	S GEAR ITURE GEAR RD	PILL LOCA	COMM			aga SYRACUSE 546-5801	
CONT. FACTOR: Human Error SPILL REPORTED BY: Other FACILITY TYPE: Commercial/Industrial WATERBODY:								
	LLED WITH CU	TTING OIL WAS PUN ND IN PROCESS OF (CONTAI	INED ABOU	IT 1 PINT WEN [.]
MATERIAL cutting oil		CLASS Petroleum	_	PILLED 300.00 G	RECO 299.00	VERED) G	RESOURC Soil,	ES AFFECTED
COMPANY NEW PROCESS	GEAR	POT ADDRESS 6600 NEW VENT	ENTIAL S		_	E N JAM	ITACT ES BROWN) 546-5801	
Tank No. Tank		Cause	Sou	rce	Test Meth	od	Leak Rate	Gross Failure
Operator punctur bed. Product lea	ed a 300 gallon ked from seam	tote containing emulsi in trailer onto loading b	oay pad. Op	o-Tech cal	lled out by NPO	G. Produ	ct was	

recovered, trailer was rinsed and pad cleaned. Less then one gallon of product was released to a storm drain on the pad that discharges to NPG storm water retension pond.

PIN T & A COST CENTER

CLASS: C4 **CLOSE DATE:** 05/17/2007 False **MEETS STANDARDS:**

05/16/2007 Created On: FOIL196008 Last Updated: 05/29/2007 Date Printed: 12/12/2018 34



B4

CLOSE DATE: 11/10/2009

NYSDEC SPILL REPORT FORM



DEC REGION: SPILL NAME:	7 PLANT			SPILL NI		09089 KCKE		
CALLER NAME CLR'S AGENC CALLER'S PHO		A FIRE CONTROL 881		NOTIFIE	R'S NAME: R'S AGENCY: R'S PHONE:	SYRAC SYRAC		
SPILL DATE: CALL RECEIV	ED DATE:	11/09/2009 11/09/2009	SPILL TI	ME: ED TIME:	10:52 pm 11:25 pm		DISPATCH AMMACB	
PLACE: STREET: CONTACT:	PLANT 6600 NEW VEN CATHY	<u>SPI</u> TURE GEAR DRIVE	LL LOC	COMN	ITY: I/CITY: IUNITY: ACT PHONE:		aga SYRACUSE 135-8881	
CONT. FACTOR: Traffic Accident FACILITY TYPE: Commercial/Industrial					REPORTED B	NONE		
CALLER REMARKS: 10 gallons went onto pavement; clean up by FD								
MATERIAL gasoline		CLASS Petroleum		SPILLED 10.00 G	RECO 10.00	VERED G	RESOURC Imp Surf,	ES AFFECTED
POTENTIAL SPILLERS COMPANY VAN OFF A LOADING DOCK ADDRESS 6600 NEW VENTURE GEAR DRIVE EAST SYRACUS CATHY (315) 435-8881								
Tank No. Tank	Size Material	Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMARKS: van drove off loading dock, causing gas tank to rupture and lose contents to pavement. East Syracuse FD controlled with absorbent. NVG drummed for disposal.								
PIN	<u>T 8</u>	<u> </u>	COST C	<u>ENTER</u>				

Created On: 11/09/2009

Date Printed: 12/12/2018

Last Updated: 11/10/2009

50|L196009 | 35|

MEETS STANDARDS:

True





DEC REGION:	7			SPILL NUMBER: 1209735				
SPILL NAME:	MAGNA F	ACILITY		DEC LEAD	D :	RJBR	AZEL	
CALLER NAME		ON MCDONALD		NOTIFIER	-		ON MCDON	ALD
CLR'S AGENCY: P.T.L. INC				NOTIFIER	'S AGENCY:	P.T.L. II	VC .	
CALLER'S PHO	ONE: 334850	1487		NOTIFIER	'S PHONE:	334850	1487	
SPILL DATE:		11/05/2012	SPILL T	IME:	1:05 pm		DISPATCH	IER:
CALL RECEIV	ED DATE:	11/08/2012	RECEIV	ED TIME: _	3:04 pm		jwmaher	
		SF	PILL LOC	ATION				
PLACE:	MAGNA FAC	CILITY		COUNT	Υ:	Ononda	aga	
STREET:	STREET: 6600 NEW VENTURE GEAR DR			TOWN/CITY:		Dewitt		
				COMMU	JNITY:	DEWIT	Γ	
CONTACT:	CONTACT: SHANNON MCDONALD CONTACT PHO				CT PHONE:	33485	01487	
CONT. FACTO	R: Oth	er	REPORTED B	Y: Other				
FACILITY TY	PE: Con	nmercial/Industrial		WATERBODY:				
CALLER REI Soil sample	_	Inknown type oil.						
MATERIAL unknown petrolei	um	CLASS Petroleur	n	SPILLED	RECO	VERED	RESOURC Soil, GW,	ES AFFECTED
		<u>P01</u>	TENTIAL	SPILLER	<u>s</u>			
COMPANY ONX 1 LLC		ADDRESS NY				CON	ITACT	
Гаnk No. Tank	Size Materi	al Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure

DEC REMARKS:

Phase 2 investigation of site has discovered a black, oily substance in several boreholes that have been advanced into the ground. Samples have been collected and sent to the lab. A full report will be forwarded to NYSDEC in about a month.

1/14/13 - Call Consultant who reported "spill". Report to be issued soon.

2/27/13 - Frank Bifera of Hiscock Barclay submitted Phase II and Phase IIA- loaded in edocs

2/25/13 - Frank Bifera submits correspondence to Joe Sluzar (DEC Region 7 Regional Attorney) which identifies 6 Areas of concern. loaded in edocs

Created On: 11/08/2012 FOIL196010

Date Printed: 12/12/2018 Last Updated: 08/22/2013 36





DEC REGION: 7 SPILL NUMBER: 1209735

SPILL NAME: MAGNA FACILITY DEC LEAD: RJBRAZEL

PIN T&A COST CENTER

CLASS: C4 CLOSE DATE: 08/16/2013 MEETS STANDARDS: False

Created On: 11/08/2012 Date Printed: 12/12/2018

Last Updated: 08/22/2013 FOIL196011 37



CLASS:

А3

CLOSE DATE: 08/16/2013

NYSDEC SPILL REPORT FORM



DEC REGION: SPILL NAME:	7 ONX 1 LUBE		SPILL DEC L	NUMBER: EAD:	1215916 RJBRAZEL	
CALLER NAME CLR'S AGENC CALLER'S PHO			NOTIF	ER'S NAME: ER'S AGENCY: ER'S PHONE:		
SPILL DATE: CALL RECEIV			SPILL TIME: RECEIVED TIME	2:33 pm 2:33 pm	DISPATO JJCLAR	
PLACE: STREET: CONTACT:	ONX 1 LUBE 6600 NEW VENTURE JAMES COHER		TOV COM	JNTY: VN/CITY: MMUNITY: NTACT PHONE:	Onondaga Dewitt EAST SYRACUSE (315) 440-5453	
CONT. FACTO				L REPORTED B	SY: Other SANDERS CRE	ΕK
	MARKS: anders creek, haz mat o					
MATERIAL cutting oil		CLASS Petroleum	SPILLE 1,000.0		SW, Sewe	CES AFFECTED er,
COMPANY ONX 1 LUBE		DDRESS	NTIAL SPILLI RE GEAR RD E		CONTACT E N JAMES COHEI (315) 440-5453	
Tank No. Tank	Size Material	Cause	Source	Test Meth	od Leak Rate	e Gross Failure
DEC REMAR	KS:					
<u>PIN</u>	<u>T & A</u>	<u>c</u>	COST CENTER			

Created On: 02/27/2013 FOIL196012
Date Printed: 12/12/2018 Last Updated: 08/22/2013 38

MEETS STANDARDS:

False





DEC REGION:	7			SPILL N	JMBER:	1305696
SPILL NAME:	ONYX 1			DEC LEA	AD:	KCKEMP
CALLER NAME	: RORY	WOODNANSEE		NOTIFIE	R'S NAME:	RORY WOODNANSEE
CLR'S AGENC	ENCY: CNS ENGINEERS			NOTIFIE	R'S AGENCY:	CNS ENGINEERS
CALLER'S PHONE: (315) 455-2000			NOTIFIE	R'S PHONE:	(315) 455-2000	
SPILL DATE:		08/28/2013	SPILL T	IME:	2:00 pm	DISPATCHER:
CALL RECEIV	ED DATE:	08/28/2013	RECEIV	ED TIME:	2:34 pm	PJPUGSLE
			SPILL LOC	ATION		
PLACE:	ONYX 1			COUN	TY:	Onondaga
STREET:	6600 NEW	VENTURE GEAR DR		TOWN		Dewitt
				COMM	IUNITY:	East Syracuse
CONTACT:	ROBERT	TRAFFORD		CONT	ACT PHONE:	(954) 214-5556
CONT. FACTO	R: Eq	uipment Failure		SPILL	REPORTED B	s Y : Other
FACILITY TY	PE: Co	mmercial/Industrial		WATE	RBODY:	
CALLER REI						

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
lube oil	Petroleum			Soil,

POTENTIAL SPILLERS

COMPANYADDRESSCONTACTPROPERTY OWNER6600 NEW PROCESS GEAR RD DEWITT NYROBERT TRAFFORD

(954) 214-5556

Tank No.	Tank Size 12,000	Material lube oil	Cause Unknown	Source Unknown	Test Method	Leak Rate 0.00	Gross Failure
2	12,000	lube oil	Unknown	Unknown		0.00	
3	12,000	lube oil	Unknown	Unknown	00	0.00	
4	12,000	lube oil	Unknown	Unknown		0.00	
5	12,000	lube oil	Unknown	Unknown		0.00	
6	12,000	lube oil	Unknown	Unknown		0.00	
7	12,000	lube oil	Unknown	Unknown		0.00	
8	12,000	lube oil	Unknown	Unknown		0.00	
9	12,000	lube oil	Unknown	Unknown		0.00	
10	12,000	lube oil	Unknown	Unknown	00	0.00	

DEC REMARKS:

spill closed. RP called contractor for clean up.

8/28/2013 - C&S Engineers overseeing cleanup using owner's demolition crews. Contaminated groundwater to be pumped from excavation over next few days and treated using onsite industrial wastewater pretreatment plant.

Created On: 08/28/2013 FOIL196013

Date Printed: 12/12/2018 Last Updated: 10/08/2013 39





DEC REGION:	7	SPILL NUMBER:	1305696
SPILL NAME:	ONYX 1	DEC LEAD:	KCKEMP

Contaminated pea stone backfill around tanks to be excavated and disposed of off site, then sidewall and bottom soil samples to be secured.

8/29/2013 - UST removal completed and tanks 1-12 all removed. Minor contamination observed on groundwater at base of excavation, which is being pumped to onsite wwtp for treatment and disposal. C&S starting to screen uncontaminated pea gravel for onsite reuse so they can access base of sides and bottom of excavation for sampling.

9/24/2013 - Closure report received and filed. KCKemp

10/8/2013 - NFA letter prepared and distributed. Spill closed. KCKemp

PIN T&A COST CENTER

CLASS: C3 CLOSE DATE: 10/07/2013 MEETS STANDARDS: False

Created On: 08/28/2013 FOIL196014

Date Printed: 12/12/2018 Last Updated: 10/08/2013 40





DEC REGION:	7					SPILL N	UMBER:	1610	499	
SPILL NAME:	BEF	RNIE BUS	3			DEC LEAD:		SMF	ITZGE	
CALLER NAME	: F	RANK				NOTIFIE	R'S NAME:	FRANK	(
CLR'S AGENCY		BERNIE B	US			NOTIFIE	R'S AGENCY:	BERNI	E BUS	
CALLER'S PHO	NE: (315) 336-	3950 249			NOTIFIE	R'S PHONE:	(315) 3	36-3950 249	
SPILL DATE:			02/22/201	7	SPILL	TIME:	8:00 am		DISPATCH	IER:
CALL RECEIVE	ED DA	ATE:	02/22/201	7	RECEI	VED TIME:	8:07 am		DABRUCE	
				SP	ILL LO	CATION				
PLACE:	BERN	IIE BUS				COUN	TY:	Onond	aga	
STREET:	6600	NEW VEI	NTURE				I/CITY:	Dewitt		
-						_	IUNITY:	DEWIT	П	
CONTACT:	FRAI	NK				_ CONT	ACT PHONE:			
CONT. FACTOR	₹:	Other				_ SPILL	REPORTED E	3Y: Othe	r	
FACILITY TYP	PE:	Comm	ercial Vehic	le		_ WATE	RBODY:			
CALLER REMARKS: spill to paved area/clean up underway										
MATERIAL liesel				CLASS Petroleum	1	SPILLED 3.00 G	RECO	VERED	RESOURC	ES AFFECTED
				POT	ENTIAL	_ SPILLEF	RS			
COMPANY			ADDRE	ESS				CO	NTACT	
BERNIE BUS			NY							
ank No. Tank	Size	Material	C	Cause	S	ource	Test Meth	od	Leak Rate	Gross Failure
DEC REMARK	⟨S:									
Spill due to overfi disposal. No reso			d cleaned uլ	p with spee	edy dry ar	nd placed in	barrels, Eagan	Environ	mental to do	
PIN		Ţ	<u>& A</u>		COST	CENTER				
				/23/2017				False		

Created On: 02/22/2017

Date Printed: 12/12/2018

Last Updated: 02/23/2017

FOIL196015

41





DEC REGION:	7					SPILL NU	JMBER:	92086	676	
SPILL NAME:	NE	W PROC	ESS GEA	AR .		DEC LEA	AD:	HDW	ARNER	
CALLER NAMI CLR'S AGENC CALLER'S PHO	Y:					NOTIFIER	R'S NAME: R'S AGENCY: R'S PHONE:			
SPILL DATE:	/ED D/	ATE:	10/27/1		SPILL T	TIME: /ED TIME:	6:56 pm 7:34 pm		DISPATCH	IER:
				SI	PILL LOC	CATION				
PLACE:	NEW	PROCE	SS GEAR			COUN	TY:	Ononda	aga	
STREET:	6600	CHRYSL	ER DRIV	Έ		TOWN			nknown *****	
CONTACT:						_	IUNITY: ACT PHONE:	EASTS	SYRACUSE	
CONTACT.							ACT PHONE.			
CONT. FACTO	DR:		Test Failu			SPILL	REPORTED E	3Y: Tank	Tester	
FACILITY TYPE: Commercial/Industrial					WATE	RBODY:				
CALLER RE TANK TES										
MATERIAL				CLASS		SPILLED		VERED		ES AFFECTED
gasoline				Petroleur	n	0.00	0.00		Soil,	
				<u>PO</u>	ΓΕΝΤΙΑL	. SPILLEF	<u>RS</u>			
COMPANY NEW PROCESS	S GEA	R		DRESS 0 CHRYSLEF	R DRIVE	EAST SYR	ACUSE NY	CON	NTACT	
Tank No. Tank	Size	Material	I	Cause	Sc	ource	Test Meth	nod	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 20		a transla	tion this s	pill Lead_DE	C Field wa	s "HW"				
<u>PIN</u>		<u>T</u>	- & A		COST	ENTER				
CIASS: C3		CI OSE	DATE:	02/09/1995		MEETS ST	TANDADDS:	False		

Created On: 12/09/1992

Date Printed: 12/12/2018

Last Updated: 02/09/1995

FOIL196016

42





DEC REGION:	7					SPILL N	UMBER	:	9412	146	
SPILL NAME:	NE	W PROC	ESS GE	AR		DEC LEA	AD:	-	CFM	ANNES	
CALLER NAM	E:[DICK BIL	HARZ			NOTIFIE	R'S NAI	ИE: _			
CLR'S AGENC	1: Y :	NEW PR	OCESS	GEAR		NOTIFIE	R'S AGI	ENCY:_			
CALLER'S PH	ONE <u>: (</u>	(315) 432	2-4241			NOTIFIE	R'S PHO	ONE: _			
SPILL DATE:			12/09	/1994	SPILL	ГІМЕ:	2:30	om		DISPATCH	IER:
CALL RECEIV	/ED D	ATE:	12/09	/1994	RECEI	/ED TIME:	4:12	om			
				S	PILL LO	CATION					
PLACE:	NEW	PROCE	SS GEA	R		COUN	ITY:	_	Onond	aga	
STREET:	6600	CHRYSI	ER DRI	VE		_	V/CITY:	-		nknown *****	
						_	//UNITY:	-	EASI	SYRACUSE	
CONTACT:						CONT	ACT PH	IONE:			
CONT. FACTO	DR:	Equip	ment Fa	ilure		SPILL	REPOR	RTED B	Y: Resp	onsible Party	1
FACILITY TY	PE:	Comr	nercial/Ir	ndustrial		_ WATE	RBODY	′ :			
	HEAT	FUEL S		TANK,TESTEI IN PROPER F CLASS				IS FAU			UP HEATER
#2 fuel oil				Petroleu	m	0.00 G		0.00 G		Soil,	LO AIT LOTED
				PO	TENTIAL	SPILLER	RS				
COMPANY NEW PROCES	S GEA	١R		D DRESS 00 CHRYSLE	R DRIVE	EAST SYR	RACUSE	ZZ	COI	NTACT	
									(315	5) 432-4241	
Tank No. Tank	Size	Materia	I	Cause	Sc	ource	Tes	st Metho	od	Leak Rate	Gross Failure
DEC REMAR	RKS:										
Prior to Sept, 20 09/28/95: This i LEAK.							slation of	the old	spill file	: SUPPLY LI	NE
PIN		<u>1</u>	Г <u>& А</u>		COST	ENTER					
CLASS: C3		CLOSE	DATE:	12/13/1994		MEETS S	TANDAI	RDS:	False		

Created On: 12/15/1994 FOIL196017

Date Printed: 12/12/2018 Last Updated: 11/28/1997 43





	7					0000	100	
DEC REGION:	7			SPILL N		9603		
SPILL NAME:	NEW VENTU	RE GEAR PLANT		DEC LEA	AD:	CFMA	ANNES	
CALLER NAME:	: PHYLLIS F	PRINCE		NOTIFIEI	R'S NAME:	LEON S	SMITH	
CLR'S AGENCY	: NEW VEN	TURE GEAR		NOTIFIEI	R'S AGENCY:	NEW VI	ENTURE GEAR	
CALLER'S PHO	NE: (315) 438-2	2716		NOTIFIE	R'S PHONE:	(315) 43	38-2716	
SPILL DATE:		06/06/1996	SPILL T	IME:	10:00 am		DISPATCHER:	
CALL RECEIVE	D DATE:	06/06/1996	RECEIV	ED TIME:	10:29 am			
		SP	ILL LOC	ATION				
PLACE:	NEW VENTURI	E GEAR PLANT		COUN	TY:	Ononda	aga	
STREET:	6600 CHRYSLE	R DRIVE		TOWN			nknown ****	
-				COMM	IUNITY:	EAST S	SYRACUSE	
CONTACT:	PHYLLIS PRIN	ICE		CONT	ACT PHONE:	(315)	438-2716	
CONT. FACTOR	R: Human	Error		SPILL	REPORTED E	BY: Resp	onsible Party	
FACILITY TYP	E: Comme	ercial/Industrial		_	RBODY:		•	
CALLER REM transport of		able diesel tank on so	uth end of	plant				
·		er spilling approx 5 gal						
outside and	tarik tipped ove	er spilling approx 5 gai	ions of pro	duci				
spill contain	ed and being cl	•						
MATERIAL diesel		CLASS Petroleum	า	SPILLED 0.00 G	RECO 0.00 (VERED	RESOURCES AF Soil,	FECTED
		<u> POT</u>	ENTIAL	SPILLEF	<u>RS</u>			
COMPANY NEW VENTURE	GEAR PLANT	ADDRESS 6600 CHRYSLER	DR EAS	ST SYRACI	JSE NY 1305	_	ITACT 'LLIS PRINCE	
						(315	i) 438-2716	

Tank No. Tank Size Material Cause Source Test Method Leak Rate Gross Failure

DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "CM"

PIN T & A COST CENTER

CLASS: D5 CLOSE DATE: 08/06/2002 MEETS STANDARDS: False

Created On: 06/06/1996

Date Printed: 12/12/2018

Last Updated: 08/06/2002

FOIL196018

44





DEC REGION: SPILL NAME:		URE GEAR		SPILL NU		9603 BFM	347 ATTHE	
CALLER NAME CLR'S AGENC CALLER'S PHO SPILL DATE:	Y: NEW VE	NTURE GEAR 3-2716 06/10/1996	SPILL T	NOTIFIER NOTIFIER	R'S NAME: R'S AGENCY: R'S PHONE: 4:30 pm	JOHN I		
CALL RECEIV	'ED DATE:	06/10/1996	RECEIV	ED TIME:	5:34 pm			
PLACE: STREET: CONTACT:	NEW VENTUE	RE GEAR LER DRIVE	PILL LOC	COUNT TOWN/	CITY:	DEWIT	nknown ****	
CONT. FACTO		oment Failure mercial/Industrial		•	REPORTED B	Y: Resp	onsible Party	
	M A VALVE O	N STORAGE TANK. S OCK COVERED SOIL						
MATERIAL pakite (soap)		CLASS Other		SPILLED 15.00 G	RECO 15.00	VERED G	RESOURCE Soil,	ES AFFECTED
COMPANY NEW VENTURE	E GEAR	POT ADDRESS 6600 CHRYSLEF		SPILLER	_	PH)	NTACT YLLIS PRINC 5) 438-2716	E
Tank No. Tank	Size Materia	I Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure
	04 data transla R TO SPILL 95	ation this spill Lead_DE0 507675. MONITORING			L BE DONE FO	OR THE	TANK REMC	OVAL
<u>PIN</u>]	Г&А	COST C	<u>ENTER</u>				
CLASS: C3	CLOSE	DATE: 06/10/1996		MFFTS ST	ANDARDS:	False		

Created On: 06/10/1996

Date Printed: 12/12/2018

Last Updated: 10/29/1996

FOIL196019

45





								Constitution.
DEC REGION:	7		s	PILL NUMBE	R: _	96063	89	
SPILL NAME:	NEW PROCES	S GEAR	D	EC LEAD:	_	CFMA	NNES	
CALLER NAME	: RICHARD BI	LHARZ	N	OTIFIER'S NA	ME: F	RICHAR	RD BILHARZ	
CLR'S AGENCY	r: NEW PROCI	ESS GEAR	N	OTIFIER'S AC	ENCY:	NEW PF	ROCESS GE	AR
CALLER'S PHO	ONE: (315) 432-42	41	N	OTIFIER'S PH	IONE: _(315) 43	2-4241	
SPILL DATE:		08/18/1996	SPILL TIME	12:0	0 pm		DISPATCH	ER:
CALL RECEIV	ED DATE:	08/18/1996	RECEIVED	TIME: 8:47	' pm			
		SF	PILL LOCAT	ΓΙΟΝ				
PLACE:	NEW PROCESS	GEAR		COUNTY:		Ononda	ıga	
STREET:	6600 CHRYSLER	DRIVE		TOWN/CITY			known *****	
				COMMUNIT	_		YRACUSE	
CONTACT:	RICHARD GEAF	<u> </u>		CONTACT P	PHONE: _	(315) 4	132-4241	
CONT. FACTO	R: Equipme	nt Failure		SPILL REPO	RTED BY	: Respo	onsible Party	
FACILITY TY	PE: Non Majo	or Facility > 1,100 ga	al	WATERBOD	Υ:			
BROKE CA	OF MATERIAL S AUSING SPILL S PERSON CHRIS AS BEEN SHUT D	PILL CLEANED BY	OPTECH (3°	ED ON BOILEI 15) 463-1643 AVAIL AT TH				
MATERIAL nercury		CLASS Hazardou	SP us Material 3.0	PILLED 00 L	RECOV 3.00 L	ERED	RESOURCE Soil,	ES AFFECTED
		<u>PO1</u>	TENTIAL SE	PILLERS				
COMPANY NEW PROCESS	GEAR	ADDRESS 6600 CHRYSLEA	AR DR EAST	SYRACUSE	NY 1305	7 RICH	I TACT HARD GEAR) 432-4241	
ank No. Tank	Size Material	Cause	Sourc	e Te	est Metho	d	Leak Rate	Gross Failure
DEC REMAR	KS:							
Prior to Sept, 200	04 data translation	this spill Lead_DE0	C Field was "C	:M"				
PIN	Т&.	Α	COST CEN	TER				

Created On: 08/18/1996

Date Printed: 12/12/2018

Last Updated: 10/08/1996

FOIL196020

46





DEC REGION: 7 SPILL NUMBER: 9606389

SPILL NAME: NEW PROCESS GEAR **DEC LEAD**: CFMANNES

CLASS: C3 CLOSE DATE: 08/30/1996 MEETS STANDARDS: False

Created On: 08/18/1996

Date Printed: 12/12/2018

Last Updated: 10/08/1996

47





DEC REGION:					_ SPILL NU	-	96080		
SPILL NAME:	NE	W VENTU	RE		_ DEC LEA	D: _	CFMA	ANNES	
CALLER NAME	≣: <u> </u>	JOHN EME	DELSOHN		NOTIFIER	'S NAME:	NRC		
CLR'S AGENC	Y:!	EPA			NOTIFIER	'S AGENCY:_			
CALLER'S PHO	ONE: ((908) 548-8	3730		NOTIFIER	'S PHONE: _			
SPILL DATE:		_	09/26/1996	SPILL T	IME:	10:30 am		DISPATCH	IER:
CALL RECEIV	ED D	ATE: _	09/26/1996	RECEIV	ED TIME:	12:25 pm		-	
			5	SPILL LO	CATION				
PLACE:	NEW	VENTURE	Ε		COUNT	Γ Y :	Ononda	aga	
STREET:	6600	CHRYSLE	ER DRIVE		_ TOWN/	-		nknown *****	
CONTACT	104	IN ZELL			COMM	-		SYRACUSE	
CONTACT:	<u> </u>	IN ZELL			CONTA	ACT PHONE:	(315)	432-4187	
CONT. FACTO	R:	Human	Error		_ SPILL I	REPORTED B	Y : Fede	ral Governme	ent
FACILITY TY	PE:	Comme	ercial/Industrial		WATER	RBODY:			
			wing material to spil						
MATERIAL lube oil			CLASS Petrole		SPILLED 1,200.00 G		/ERED	Sewer,	ES AFFECTED
			<u>PC</u>	DTENTIAL	SPILLER	<u>S</u>			
COMPANY NEW VENTURE	Ē		ADDRESS 6600 CHRYSLE	ER DR EA	ST SYRACU	JSE NY		NTACT IN ZELL	
							(315	5) 432-4187	
Tank No. Tank	Size	Material	Cause	So	ource	Test Metho	od	Leak Rate	Gross Failure
DEC REMAR	KS:								
Prior to Sept, 20	04 dat	ta translatio	on this spill Lead_DI	EC Field wa	s "CM"				
<u>PIN</u>		T 8	<u>& A</u>	COST	ENTER				

FOIL196022 Last Updated: 11/15/1996 Date Printed: 12/12/2018 48

MEETS STANDARDS:

False

09/26/1996 Created On:

D6

CLOSE DATE: 09/30/1996

CLASS:





							CONSCI TOUR			
DEC REGION:	7			SPILL N	JMBER:	9700843				
SPILL NAME:	NEW PROC	ESS GEAR		DEC LEA	AD:	CFMANNES				
CALLER NAME	: RICHARE) BILHARZ		NOTIFIER	R'S NAME:	JOHN GAROFALO				
CLR'S AGENC	Y: NEW PRO	DCESS GEAR		NOTIFIER'S AGENCY: PLANT MANAGER						
CALLER'S PHO	ONE: (315) 432	-4241		NOTIFIER	R'S PHONE:					
SPILL DATE:		04/19/1997	SPILL T	IME:	8:45 am	DISPATCHER:				
CALL RECEIV	ED DATE:	04/19/1997	RECEIV	ED TIME:	10:43 am					
		S	PILL LOC	ATION						
PLACE:	NEW PROCES	SS GEAR		COUN	TY:	Onondaga				
STREET:	6600 CHRYSL	ER DRIVE		TOWN						
				-	IUNITY:	DEWITT				
CONTACT:	RICHARD BII	_HARZ		CONT	ACT PHONE:	(315) 432-4241				
CONT. FACTO	R: Equip	ment Failure		SPILL REPORTED BY: Responsible Party						
FACILITY TYPE: Commercial/Industrial				WATE	RBODY:					
INDUSTRI. REPAIR BI	AL WASTE SE EING MADE	E WITHIN THE PLAN' WER LINE - LINE IS : 1% OIL 96% WATER								
MATERIAL		CLASS		SPILLED	RECO	VERED RESOURC	ES AFFECTED			
		<u>PO</u>	TENTIAL	SPILLEF	<u>RS</u>					
COMPANY NEW PROCESS	S GEAR	ADDRESS 6600 CHRYSLE	RDR EAS	ST SYRACI	USE NY 1305	CONTACT 7- RICHARD GEAR (315) 432-4241	!			
ank No. Tank	Size Material	Cause	So	urce	Test Meth	od Leak Rate	Gross Failure			
DEC REMAR Prior to Sept, 200		ion this spill Lead_DE	EC Field was	s "CM"						
PIN	т	. & Д	COST C	FNTFR						

Created On: 04/19/1997

Date Printed: 12/12/2018

Last Updated: 04/19/1997

49





DEC REGION: 7 SPILL NUMBER: 9700843

SPILL NAME: NEW PROCESS GEAR **DEC LEAD**: CFMANNES

CLASS: C3 CLOSE DATE: 09/03/1997 MEETS STANDARDS: False

Created On: 04/19/1997

Date Printed: 12/12/2018

Last Updated: 04/19/1997

50





DEC REC		7		VED DD			SPILL NI		9712032 CFMANNES			
SPILL NA	AME:	960	00 CHRYSI	KER DR			DEC LEA	AD:	CFIVIA	ANNES		
CALLER	NAME:	F	PHYLLIS P	RINCE			NOTIFIE	R'S NAME:	PHYLL	IS PRINCE		
CLR'S AC	GENCY	:^	NEW VENT	URE GE	AR		NOTIFIE	R'S AGENCY:	NEW V	ENTURE GE	AR	
CALLER'	S PHO	NE <u>: (</u>	315) 438-2	716			NOTIFIE	R'S PHONE:	(315) 4	38-2716		
SPILL D	ATE:		_	01/28/19	98	SPILL T	IME:	9:30 am		DISPATCH	IER:	
CALL RE	ECEIVE	D D	ATE:	01/28/19	998	RECEIV	ED TIME:	11:30 am				
					SP	ILL LOC	ATION					
PLACE	: 6	600	CHRYSKE	R DR			COUN	TY:	Onond	aga		
STREE	T: 6	600	CHRYSLE	R DRIVE			_	TOWN/CITY:		***** Unknown *****		
							-	IUNITY:		SYRACUSE		
CONTA	ACT: _	CALI	LER				CONT	ACT PHONE:	(315)	438-2716		
CONT. F	ACTOR	₹:	Human	Error			SPILL	REPORTED E	Y: Affec	ted Persons		
FACILI [*]	ACILITY TYPE: Commercial Vehicle					WATE	RBODY:					
		ed th	at driver w	as filling	his tank and	overfilled.	operator w	as away from t	ruck at ti	me of spill. sp	oill is being	
MATERIAL	<u>_</u>				CLASS		SPILLED	RECO	VERED	RESOURC	ES AFFECTED	
					POT	ENTIAL	SPILLEF	<u> </u>				
COMPAN' FRANKS	-	ΙE			RESS ROYAL AVE	E NIAGA	RA FALLS	NY 14303-	COI	NTACT		
									(716	6) 855-2212		
Tank No.	Tank S	Size	Material		Cause	So	urce	Test Meth	iod	Leak Rate	Gross Failure	
DEC RE	EMARK	S:										
Prior to Se	pt, 2004	4 dat	a translatio	on this sp	ill Lead_DEC	Field was	s "CM"					
PIN	<u> </u>		<u>T 8</u>	& A		COST C	<u>ENTER</u>					
CLASS:	C3		CLOSE D	ATE: C)4/13/1998		MEETS ST	ΓANDARDS:	False			

Created On: 01/28/1998

Date Printed: 12/12/2018

Last Updated: 01/28/1998

51





DEC REGION: SPILL NAME:	7 TANK FARM	1		SPILL NUMBER: DEC LEAD:		9806403 CFMANNES		
CALLER NAME CLR'S AGENC CALLER'S PHO	Y: NEW VEN	ITURE GEAR		NOTIFIE	R'S NAME: R'S AGENCY: R'S PHONE:	EMPLOYEES		
SPILL DATE: CALL RECEIV	ED DATE:	08/24/1998 08/24/1998	SPILL T	IME: ED TIME:	11:00 am 1:00 pm	_ DISPATCHER:		
			SPILL LOC	ATION				
PLACE: TANK FARM STREET: 6600 CHRYSLER DRIVE				COUN TOWN		Onondaga ***** Unknown ***** EAST SYRACUSE		
CONTACT:	PHYLLIS PRII	NCCE		CONT	ACT PHONE:	(315)	438-2716	
CONT. FACTOR: Equipment Failure SPILL REPORTED BY: Responsible Party								
FACILITY TY		WATE	RBODY:					
CALLER REMARKS: ONE OF THE OIL PUMPS THAT CONTAINS SOLUABLE OIL SPRAYED OIL & IT GOT INTO A STORM DRAIN - CLEAN UP IN PROGRESS								
MATERIAL		CLA	ASS	SPILLED	RECO	VERED	RESOURC	ES AFFECTED
			POTENTIAL	SPILLER	RS			
COMPANY NEW VENTURE	E GEAR	ADDRESS ZZ				COI	NTACT	
Tank No. Tank	Size Material	Caus	e So	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 20		ion this spill Lead	_DEC Field was	s "CM"				
<u>PIN</u>	Ţ	<u>& A</u>	COST C	ENTER	_			
CLASS: C3	CLOSE	DATE: 08/31/19	998	MEETS ST	ANDARDS:	False		

Created On: 08/24/1998

Date Printed: 12/12/2018

Last Updated: 01/15/1999

52





DEC REGION:	7 NEW VENTURE G	EAD		SPILL NU		9807′	176 ANNES	
SPILL NAME:	NEW VENTURE G	EAR		DEC LEA	ND:	CFIVIA	AININES	
CALLER NAME	: JIM BROWN			NOTIFIER	R'S NAME:	JIM BR	NWC	
CLR'S AGENC	r: NEW VENTURE	GEAR		NOTIFIER	R'S AGENCY:	NEW VI	ENTURE GE	AR
CALLER'S PHO	ONE: (315) 431-7089			NOTIFIER	R'S PHONE:	(315) 43	31-7089	
SPILL DATE:	09/1	1/1998	SPILL T	IME:	12:30 pm		DISPATCH	IER:
CALL RECEIV	ED DATE : 09/1	1/1998	RECEIV	ED TIME:	2:38 pm			
		SF	PILL LOC	ATION				
PLACE:	NEW VENTURE GEA			COUN	TY:	Ononda	aga	
STREET:	6600 NEW VENTURI	E GEAR DRIVE		TOWN	/CITY:		nknown *****	
				СОММ	IUNITY:	EAST S	SYRACUSE	
CONTACT:	JIM BROWN			CONT	ACT PHONE:	(315)	431-7089	
CONT. FACTO	R: Tank Overfill			SPILL	REPORTED B	Y: Affect	ed Persons	
FACILITY TY	PE: Institutional,	Educational, Go	v., Othe	WATE	RBODY:			
CALLER REM CALLER S MATERIAL	MARKS: TATED UNKNOWN C	CLASS	RFILLED 1	SPILLED	RECO	VERED	RESOURC	ES AFFECTED
		PO1	TENTIAL	SPILLER	RS			
COMPANY UNKNOWN	A	DDRESS NY				CON	NTACT	
Tank No. Tank	Size Material	Cause	So	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 200	KS: 04 data translation this	s spill Lead_DE0	C Field was	s "CM"				
<u>PIN</u>	<u>T & A</u>		COST C	ENTER				
CLASS: C3	CLOSE DATE:	10/31/1998		MEETS ST	ANDARDS:	False		

Created On: 09/11/1998

Date Printed: 12/12/2018

Last Updated: 01/19/1999

53





DEC REGION:	7	SPILL NI	UMBER:	9810679				
SPILL NAME:	NEW VENTURE GEAR	DEC LEA	AD:	CXROSSI				
CALLER NAME CLR'S AGENCY			R'S NAME: R'S AGENCY:	DIEDER HEIDERMANN NEW VENTURE GEAR				
CALLER'S PHO	NE: (315) 438-2716	NOTIFIEI	R'S PHONE:	(315) 438-2716				
SPILL DATE:	11/22/1998	SPILL TIME:	12:00 pm	DISPATCHER:				
CALL RECEIVE	ED DATE: 11/23/1998	RECEIVED TIME:	4:13 pm					
	SP	ILL LOCATION						
PLACE:	NEW VENTURE GEAR	COUN	TY:	Onondaga				
STREET:	6600 NEW VENTURE GEAR DRIVE		I/CITY:	***** Unknown *****				
	DUVI ICO DDINOS		IUNITY:	EAST SYRACUSE				
CONTACT:	PHYLISS PRINCE	CONT	ACT PHONE:	(315) 438-2716				
CONT. FACTO	R: Equipment Failure	SPILL	SPILL REPORTED BY: Affected Persons					
FACILITY TYPE	PE: Commercial/Industrial	WATE	RBODY:					
CALLER REMARKS: WORK BEING DONE AT ABOVE LOCATION. LINE FAILURE ON A PIECE OF EQUIPMENT CAUSED SPILL. CALLER TRYING TO GET FURTHER INFO ON RESPONSIBLE PARTY. CALLER REQUESTING CALL BACK FROM DEC REP.								
MATERIAL	CLASS	SPILLED	RECO	VERED RESOURCES AFFECTED				

POTENTIAL SPILLERS

COMPANY ADDRESS CONTACT ATLANTIC RIGGING **UNKNOWN** UNKNOWN SYRACUSE NY

Tank No. Tank Size Material **Test Method** Cause Source Leak Rate Gross Failure

DEC REMARKS:

11/23/1998

Prior to Sept, 2004 data translation this spill Lead DEC Field was "CTR"

Atlantic Rigging was driving a crane at the site when a hydrolic line broke. The oil was sprayed over a paved area. Atlantic Rigging personell partially cleaned up area and pushed remainder into a near by stormdrain. Atlantic Rigging did not report this spill to NVG or DEC. NVG notified us next day after they found and investigated. Estimated loss was 60 gal. The storm drain contained silt and debri which adheared to the oil. The invert pipe in the stormdrain was blocked by this debri allowing the spill to end here. THe downstream storm drain was checked and no oil was present. NVG hired a contractor to clean both stormdrains that evening.

Created On: FOIL196028 Date Printed: 12/12/2018 Last Updated: 11/26/1999 54





DEC REGION: 7 SPILL NUMBER: 9810679

SPILL NAME: NEW VENTURE GEAR DEC LEAD: CXROSSI

PIN T & A COST CENTER

CLASS: C3 CLOSE DATE: 11/26/1999 MEETS STANDARDS: True

Created On: 11/23/1998 Date Printed: 12/12/2018

Last Updated: 11/26/1999 FOIL196029 55





DEC REGION:	DEC REGION: 7				_ SPILL N	UMBER:	9900368				
SPILL NAME:	Spi	II Number	9900368	8		_ DEC LE	AD:	MENASH			
CALLER NAMI CLR'S AGENC CALLER'S PHO	Y:		TURE G	EAR		NOTIFIER'S NAME: NOTIFIER'S AGENCY: NOTIFIER'S PHONE:					
SPILL DATE: CALL RECEIV	/ED D	ATE:	04/09/1		SPILL TRECEIN	ΓΙΜΕ: /ED TIME:	1:00 pm 3:36 pm		DISPATCH	IER:	
				<u>SP</u>	ILL LO	CATION					
PLACE:	Spill I	Number 99	900368			COUN	NTY:	Onond	aga		
STREET:	6600 NEW VENTURE GEAR DRIVE					N/CITY: MUNITY:		***** Unknown ***** EAST SYRACUSE			
CONTACT:	JIM	BROWN				CONT	TACT PHONE:	(315)	431-7089		
CONT. FACTO	DR:	Traffic	Acciden	t		SPILL	. REPORTED I	BY: Other	-		
FACILITY TY	PE:	Comm	ercial/Ind	dustrial		_ WATE	ERBODY:				
A BACK H MATERIAL hydraulic oil	IOE ST	TRUCK AN	I INDUS	CLASS Petroleum		SPILLED 0.00 G	RECO	OVERED	RESOURC Soil,	ES AFFECTED	
wastewater				Other		0.00 G	0.00	G	Soil,		
				POT	ENTIAL	SPILLE	RS				
COMPANY JD TAYLOR				DRESS ZZ				MIK	NTACT E WORTH 5) 463-5204		
Tank No. Tank	Size	Material		Cause	S	ource	Test Met	nod	Leak Rate	Gross Failure	
DEC REMAR	RKS:										
Prior to Sept, 20	04 dat	a translati	on this s	pill Lead_DEC	Field wa	s "MN"					
<u>PIN</u>		<u>T</u> .	<u>& A</u>		COST	CENTER					
CLASS: C3		CLOSE I	DATE:	06/03/2002		MEETS S	TANDARDS:	False			

Created On: 04/09/1999

Date Printed: 12/12/2018

Last Updated: 06/03/2002

FOIL196030

56





DEC REGION: SPILL NAME:	7 WASTE WATI	ER TREATMENT		SPILL NI		9902636 CXROSSI		
CALLER NAME CLR'S AGENC' CALLER'S PHO		URE GEAR		NOTIFIE	R'S NAME: R'S AGENCY: R'S PHONE:	NEW VE		AR
SPILL DATE: CALL RECEIV	 /ED DATE:	06/07/1999 06/07/1999	SPILL TI	ME: ED TIME:	6:00 pm 7:28 pm		DISPATCH	ER:
PLACE: STREET: CONTACT:	WASTE WATER 6600 NEW VEN PHYLISS PRIN	TREATMENT TURE GEAR DRIVE	ILL LOC	COMN	TY: I/CITY: IUNITY: ACT PHONE:	EAST S	nga known ***** SYRACUSE 132-4160	
CONT. FACTO	0	ent Failure rcial/Industrial			REPORTED B	Y: Respo	onsible Party	
	TATES THAT PE	RODUCT OVERFLOW CES ON SCENE PUM				TO STO	RM DRAIN.	OPTECH
MATERIAL waste oil/used oil	l	CLASS Petroleum		SPILLED 20.00 G	RECO 20.00	VERED G	RESOURCE Sewer,	S AFFECTED
COMPANY NEW VENTURE	E GEAR	POT ADDRESS 6600 NEW VENTU		SPILLEF R DR EA	_	E N PHY	ITACT 'LISS PRINC) 432-4160	E
Tank No. Tank	Size Material	Cause	Soi	urce	Test Meth	od	Leak Rate	Gross Failure
	04 data translatio	n this spill Lead_DEC WHICH WOIULD EN			EAN UP. CM I	PROJEC	T MANAGEF	1 .
<u>PIN</u>	<u>T 8</u>	: A	COST CI	ENTER				

Created On: 06/07/1999

Date Printed: 12/12/2018

Last Updated: 08/05/2002

FOIL196031

57

MEETS STANDARDS:

False

CLOSE DATE: 08/05/2002

CLASS:

C3





DEC REGION:	7			SPILL N	UMBER:	9906682 CXROSSI		
SPILL NAME:	NEW VEN	TURE GEAR		DEC LEA	AD:			
CALLER NAME	: PHYLLI	S PRICE		NOTIFIE	R'S NAME:	MICHAEL JARVIS		
CLR'S AGENC	NCY: NEW VENTURE GEAR				R'S AGENCY:	NEW VENTURE GEAR		
CALLER'S PHO	ONE: (315) 43	38-2716		NOTIFIE	R'S PHONE:	(315) 438-2716		
SPILL DATE:		09/04/1999	SPILL TI	ME:	12:50 pm	DISPATCHER:		
CALL RECEIV	ED DATE:	09/04/1999	RECEIVI	ED TIME:	1:26 pm			
			SPILL LOC	ATION				
PLACE:	NEW VENTU	JRE GEAR		COUN	ITY:	Onondaga		
STREET:	6600 NEW V	ENTURE GEAR DRI	IVE	TOWN	I/CITY:	***** Unknown *****		
				COMM	IUNITY:	EAST SYRACUSE		
CONTACT:	PHYLISS P	RINCE		CONT	ACT PHONE:	(315) 432-4160		
CONT. FACTO	R: Hun	nan Error		SPILL REPORTED BY: Responsible Party				
FACILITY TYPE: Commercial/Industrial			WATE	RBODY:				
CALLER REI	MARKS.							

WASTEWATER TREATMENT PLANT OPERATOR LEFT FOR THE DAY AND FORGOT TO TURN OFF THE WATER PUMP. IT SPILLED APPROX 1000 GALS - 985 OF WHICH WERE CONTAINED IN AN INDUSTRIAL SEWER -APPROX 15 GALS WERE SPILLED INTO THE STORM SEWER

MATERIAL CLASS SPILLED RECOVERED RESOURCES AFFECTED waste oil/used oil Petroleum 1,000.00 G 8,000.00 G Soil,

POTENTIAL SPILLERS

COMPANY **ADDRESS** CONTACT

NEW VENTURE GEAR 6600 NEW VENTURE GEAR DR EAST SYRACUSE IN PHYLISS PRINCE

(315) 432-4160

Tank No. Tank Size Material Cause Source **Test Method** Leak Rate Gross Failure

DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "CTR" aS OF sUNDAY SEPTEMBER 6, 8000 GAL OF WAST OIL HAD BEEN RECOVERED FROM STOM DRAINS AND POND. SPEDES OUTFALL, DOWNSTREEM, WILL BE MONITORED. BOOMS IN LINE. RECOVERY CONTINUES AS OF 9/7/1999.

INSPECTED 10/12/99. ADVISE TO SCRAPE SOIL AROUND MANHOLE AND SAMPLE ALL TCLP PARAMETERS. ALSO TO DIG UP CONTAMINATED SEDIMENTS AT THE POND. VIEWD AREA WHICH GENERATED SPILL NO 9902636. NEXT TO WASTE TANK. PIPE RUPUREDW/BACKHOE BUT CONTAMINATION WAS VISIBLE IN GRAVEL LAYER ABOUT 3 FT BGS FROM PREVIOUS SPILL. SOME SOIL REMOVED BUT THE REMAINING CONTAMINATED SOIL WILL NOT DUE TO THE POSSIBILITY OF STUCTURE COMPRAMISE. tOLD TO SMPLE SOIL FOR ALL tclp PARAMETERS PLUS PCBS. WILL BE DOING STIP. CM3 WILL HANDLE.

09/04/1999 Created On: FOIL196032 Date Printed: 12/12/2018 10/03/2001 58 Last Updated:





9906682 **DEC REGION:** 7 **SPILL NUMBER:**

NEW VENTURE GEAR CXROSSI SPILL NAME: DEC LEAD:

rEFER TO SPILL NO9908428

PIN T & A COST CENTER

CLOSE DATE: 10/02/2001 **CLASS:** А3 False **MEETS STANDARDS:**

09/04/1999 Created On:

FOIL196033 Last Updated: 10/03/2001 Date Printed: 12/12/2018 59



CLASS:

C3

CLOSE DATE: 12/06/2000

NYSDEC SPILL REPORT FORM



DEC REGION: SPILL NAME:				SPILL NUMBER: DEC LEAD:		9908428 CFMANNES		
CALLER NAME CLR'S AGENCY CALLER'S PHO	-	RE GEAR		NOTIFIER	R'S NAME: R'S AGENCY: R'S PHONE:		ENTURE GE	AR
SPILL DATE: CALL RECEIV		0/12/1999 0/12/1999	SPILL TI	ME: ED TIME:	9:00 am 9:23 am		DISPATCH	ER:
. 2, (32.	NEW PROCESS (6600 NEW VENTU PHYLISS PRINC	GEAR WWTP JRE GEAR DRIVE	LL LOC	COMM		EAST S	aga known **** SYRACUSE 132-4160	
CONT. FACTOR: Other SPILL REPORTED BY: Local Agency FACILITY TYPE: Commercial/Industrial WATERBODY:								
CALLER REM	MARKS: STRUCTION IN TH	HE FACILITY						
MATERIAL other -		CLASS Other		SPILLED 40.00 G	RECO 0.00 G	VERED	RESOURCE Soil,	ES AFFECTED
COMPANY WASTE WATER FAC	R TREATMENT	ADDRESS 6600 NEW VENTU		SPILLEF	_	PHY	ITACT 'LISS PRINC) 432-4160	E
Tank No. Tank	Size Material	Cause	Soi	urce	Test Meth	od	Leak Rate	Gross Failure
DEC REMAR Prior to Sept, 200		this spill Lead_DEC	Field was	"CM"				
<u>PIN</u>	T & A	Ā	COST CI	ENTER				

Created On: 10/12/1999

Date Printed: 12/12/2018

Last Updated: 06/03/2002

FOIL196034

60

MEETS STANDARDS:

False